

Report ID: 17,934,728 Version: 1 29 Jun 2018 Created:

Make:	Mercedes-Benz	Model:	C180	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,005	Registration:		Reg Expiry:		Engine			L
WoF Expiry:	24 May 2019	Odometer:	53,314 Kms	Good No:	17934728	Oil level	~		
VIN:	WDB2032462F740925	Next Service:	63,000	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust						Operation	~		
PT = paint defe				$\left[ \left( \right) \right]$		Noise	~		
C = crack						Clutch			~
P = pin dent	HID				7414	CV joints			~
*= decals						Wheel bearings	~		
SC = stone chips						Brakes			<u>.</u>
W = significant scuffs W W						Performance	~		
Podylog	action Commonts	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	d depth	of tyre	es)
Bonnet safety release broken						Left front 4 r			mm
						Right front		1	mm
						Left rear		7	mm
Conditions During Body Inspection:						Right rear	7 mm		
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	-		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Cood					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Arm rest o	n drivers door lo	ose			Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		L
Road Conditions During Test Drive: Dry						Central locking	2		
Road Conditions During Test Drive: Dry						Remote locking	~		
						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
									•
Inspected by: Murray Craig Date: 29 Jun 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....