

Report ID: 17,934,771 Version: 1 Created: 08 Jun 2018

Make:	Mazda	Model:	Demio	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2,007	Registration:		Reg Expiry:		Engine	1	<u> </u>		
WoF Expiry:		Odometer:	85,537 Kms	Good No:	17934771	Oil level	~			
VIN:	7AT0C12HX18501361	Next Service:	95,533kms	Service Histor	y: No	Smoke & fumes	~			
			·			Performance	~			
	port is not a warranty	oration is made	for ago and milaago	Darts have not	been dismonthed or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~			
						Performance	· ·			
Key:		-0		-161-		Radiator / Hoses (visual)	V			
S = scratch						Transmission	Transmission			
D = dent	- HE			The		Operation	~			
R = rust PT = paint defe				\int	JHH	Noise	~			
C = crack				+		Clutch	-		~	
P = pin dent					ᅰЦ	CV joints	~			
* = decals	616			The	ELIPS-	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs						Performance	~			
		Note [,] som	ne defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~			
Body Insp	pection Comments			indy not be disp		Tyres (lowest observed trea		oftyre))	
						Right front		1	mm mm	
						Left rear		1	mm	
						Right rear		2		
Conditions During Body Inspection: Dry						Spare			mm	
Under Carriage & Under Bonnet Inspection Comments						Suspension	Yes			
Ok.						Suspension performance	~			
						Steering performance				
						Shock absorbers	V			
							~			
						Air Conditioning / Heater				
Interior Comments						Operation V				
Good						Electrical / Accessories				
Seats						Head lights	~			
Carpets	Good					Tail lights	~			
· · ·	Good					Indicators	~			
Panels						Dashboard warning lights				
Dashboa	rd Good					Wipers (front & rear)	~			
						Window winder FL	~			
General	omments					Window winder FR	~			
General Comments Nice little hatch .						Window winder RL	~			
	-					Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Conditions During Test Drive: Dry						Central locking	~			
Engine Ti	ming Mechanism	Time !:=	Chain			Remote locking	~			
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)	-		~	
Evidence	огсант вен керіас	ement: N	lot Applicable	Kms:		Reversing camera			~	
Inspected by: Daryll Timms Date: 08 Jun 2018										

I have read and understood this condition guide.

Name:

Signature: