

## **Turners Certified 100 Point Check**

## Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	17,942,153
Version:	2
Created:	30 Jul 2019

Make:	Nissan	Body Style:	SUV
Model:	Dualis	VIN:	7AT0DH7HX19003840
Year:	2008	Odometer:	106,159 Kms
Road Conditions During Test Drive:	Dry		

	trical	30	Fuel Flap Release		Cooling System		Exterior					
1 E	Battery	31	Reversing Camera		55	Coolant Condition		78	Under Carriage	Good		
2 F	Headlights	32	USB Port •		56	Performance			79	Sun Roof Operation		•
3 T	Tail Lights	33	Window Lock Switch		57	Radiator/Hoses (visual)			80	Front Windscreen (no chips)	Good	
4 F	High Stop Light	Tra	nsmission and D	rive	Sus	spension		81	Back Windscreen (no chips)	Good		
5 F	Front Right Indicators	34	Operation		58	Suspension Performance		82	Side Windows (no chips)	Good		
6 F	Front Left Indicators	35	Noise		59	Steering Performance			83	Front Wiper Blades	Good	
7 F	Rear Right Indicators	36	Clutch	•	60	Shock Absorbers		84	Rear Wiper Blade	Good		
8 F	Rear Left Indicators	37	CV Joints		Wh	eels and Tyres		85	R/H Mirror	Good		
9 F	Reversing Lights	38	Wheel Bearing		61	Left Front	4.0	mm	86	L/H Mirror	Good	
10 F	Rear Reflectors	39	Wheel Balance		62	Right Front	4.0	mm	87	L/F Guard	Good	
11 H	Hazard Lights	40	Gearbox (Manual)		63	Left Rear	4.0	mm	88	R/F Guard	Good	
12 (	Courtesy Lights	41	Engine Timing	Timing Chain	64	Right Rear	5.0	mm	89	L/H Doors	Good	
13 [	Dashboard Lights	42	Evidence of Cam Belt Replacement	Not Applicable	65	Spare	Yes		90	R/H Doors	Good	
14 [	Dashboard Dimmer Switch	43	Replaced at (odometer reading)		66	Tools			91	L/H Sill	Good	
15 N	Number Plate Light	Bra	akes		Inte	terior			92	R/H Sill	Good	
16	Dashboard Warning Lights	44	Front Brakes		67	AC Operation			93	Boot/Tail Gate	Good	
17 S	Speedo	45	Rear Brakes		68	Heater Fan		94	Front Bumper	Good		
18 0	Odometer	46	Handbrake <b>V</b>		69	Seatbelts			95	Rear Bumper	Good	
19 F	Rev Counter	Key	ys and Locking		70	Horn			96	Roof	Good	
20 F	Fuel Gauge	47	Central Locking		71	Seat Heaters •			97	Bonnet	Good	
21 V	Wipers Front/Rear	48	Remote Locking		72	Sun Visors 💆			98	Fuel Cap		
22 V	Window Opener FL	49	Number of Keys 1		73	Sun Visors Lights/Mirrors			99	Mud Flaps		
23 V	Window Opener FR	Eng	gine		74	Seats	Good		100	WOF		
24 V	Window Opener RL	50	Oil Level		75	Carpets	Good					
25 V	Window Opener RR	51	Smokes and Fume	es	76	Panels	Good					
26 F	Rear View Mirrors	52	Performance		77	Dashboard	Good					
27 F	Radio (Basic Test Only)	53	Noise							ers Certification K	ey:	
28 0	CD (Basic Test Only)	54	Starter Motor						√= P ×= F			
29 E	Boot Open Switch									an lot applicable for thi	s vehicle	9

Inspected by:	Mathew Varghese	Date:	10 Jun 2019					
I have read and understood this condition guide:								
Name:		Signature:						