

Basic Vehicle Condition Guide

Report ID: 17,942,304


Version: 2

18 Jun 2019 Created:

Make: Model: Volvo S60 **Body Style:** Sedan Year: 2011 Registration: Reg Expiry: WoF Expiry: **Odometer: Good No:** 05 Feb 2020 30,276 Kms 17942304 VIN: **Next Service:** YV1FS485BB2040627 35011 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

2WD

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

_	_
Conoral	Comments
General	COMMENTS

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:**

No

Kms:

Sudhin Ramachandran Inspected by:

	Pass	Fail	N/A
Engine	1 033	1 all	IN/A
Oil level	· /		
Smoke & fumes	·		
Performance	<i>'</i>		
Noise	\(\tau \)		
Cooling System	_		
Coolant condition	V		
Performance	·		
Radiator / Hoses (visual)	•		
Transmission			
Operation	· /		
Noise	•		
Clutch			
CV joints			
Wheel bearings	<i>V</i>		
Brakes	<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>		
Performance			
	•		
Hand Brake	<i>'</i>		<u> </u>
Tyres (lowest observed tread		-	
Left front	6		mm
Right front	4.5		mm
Left rear		.5	mm
Right rear	6	.5	mm
Spare		N/A	
Suspension			
Suspension performance	-		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater	1	I	1
Operation	~		
Electrical / Accessories	ı	I	1
Head lights	~		
Tail lights	V		
Indicators			
Dashboard warning lights	~		
Wipers (front & rear)	\(\triangle \)		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	~		
	19		-

I have read and understood this condition guide.

Name:

Signature: