



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

| | |
|------------|-------------|
| Report ID: | 17,943,776 |
| Version: | 1 |
| Created: | 30 Aug 2019 |

| | | | |
|------------------------------------|--------|-------------|-------------------|
| Make: | Nissan | Body Style: | Hatchback |
| Model: | Leaf | VIN: | 7AT0DH8KX19120477 |
| Year: | 2015 | Odometer: | 57,829 Kms |
| Road Conditions During Test Drive: | Dry | | |

| Electrical | | 30 | Fuel Flap Release | ✓ | Cooling System | | 55 | Coolant Condition | ✓ | Exterior | | 78 | Under Carriage | Good | | | |
|------------|--------------------------|----|------------------------|----------------------------------|----------------|------------------|-------------------------|-------------------|------------------------|----------------------------|-------------|--------------------|-----------------------------|------|------------------|----------|------|
| 1 | Battery | ✓ | 31 | Reversing Camera | • | 56 | Performance | ✓ | 79 | Sun Roof Operation | • | 80 | Front Windscreen (no chips) | Good | | | |
| 2 | Headlights | ✓ | 32 | USB Port | • | 57 | Radiator/Hoses (visual) | ✓ | 81 | Back Windscreen (no chips) | Good | 82 | Side Windows (no chips) | Good | | | |
| 3 | Tail Lights | ✓ | 33 | Window Lock Switch | ✓ | Suspension | | 58 | Suspension Performance | ✓ | 83 | Front Wiper Blades | Good | 84 | Rear Wiper Blade | Good | |
| 4 | High Stop Light | ✓ | Transmission and Drive | | 34 | Operation | ✓ | 59 | Steering Performance | ✓ | 85 | R/H Mirror | Good | 86 | L/H Mirror | Good | |
| 5 | Front Right Indicators | ✓ | 35 | Noise | ✓ | 60 | Shock Absorbers | ✓ | Wheels and Tyres | | 87 | L/F Guard | Good | 88 | R/F Guard | Good | |
| 6 | Front Left Indicators | ✓ | 36 | Clutch | • | 61 | Left Front | 7 | mm | 62 | Right Front | 7 | mm | 89 | L/H Doors | Good | |
| 7 | Rear Right Indicators | ✓ | 37 | CV Joints | ✓ | 63 | Left Rear | 7 | mm | 64 | Right Rear | 7 | mm | 90 | R/H Doors | Good | |
| 8 | Rear Left Indicators | ✓ | 38 | Wheel Bearing | ✓ | 65 | Spare | N/A | 66 | Tools | ✓ | 91 | L/H Sill | Good | 92 | R/H Sill | Good |
| 9 | Reversing Lights | ✓ | 39 | Wheel Balance | ✓ | Interior | | 67 | AC Operation | ✓ | 93 | Boot/Tail Gate | Good | 94 | Front Bumper | Good | |
| 10 | Rear Reflectors | ✓ | 40 | Gearbox (Manual) | • | 68 | Heater Fan | ✓ | 69 | Seatbelts | ✓ | 95 | Rear Bumper | Good | 96 | Roof | Good |
| 11 | Hazard Lights | ✓ | 41 | Engine Timing | Timing Chain | 70 | Horn | ✓ | 71 | Seat Heaters | • | 97 | Bonnet | Good | 98 | Fuel Cap | ✓ |
| 12 | Courtesy Lights | ✓ | 42 | Evidence of Cam Belt Replacement | Not Applicable | 72 | Sun Visors | ✓ | 73 | Sun Visors Lights/Mirrors | ✓ | 99 | Mud Flaps | ✓ | 100 | WOF | ✓ |
| 13 | Dashboard Lights | ✓ | 43 | Replaced at (odometer reading) | | 74 | Seats | Good | 75 | Carpets | Good | | | | | | |
| 14 | Dashboard Dimmer Switch | ✓ | Brakes | | 44 | Front Brakes | ✓ | 76 | Panels | Good | 77 | Dashboard | Good | | | | |
| 15 | Number Plate Light | ✓ | 45 | Rear Brakes | ✓ | Keys and Locking | | | | | | | | | | | |
| 16 | Dashboard Warning Lights | ✓ | 46 | Handbrake | ✓ | 47 | Central Locking | ✓ | | | | | | | | | |
| 17 | Speedo | ✓ | Engine | | 48 | Remote Locking | ✓ | | | | | | | | | | |
| 18 | Odometer | ✓ | 49 | Number of Keys | 1 | 49 | Number of Keys | 1 | | | | | | | | | |
| 19 | Rev Counter | ✓ | Engine | | 50 | Oil Level | ✓ | | | | | | | | | | |
| 20 | Fuel Gauge | ✓ | 51 | Smokes and Fumes | ✓ | 51 | Smokes and Fumes | ✓ | | | | | | | | | |
| 21 | Wipers Front/Rear | ✓ | 52 | Performance | ✓ | 52 | Performance | ✓ | | | | | | | | | |
| 22 | Window Opener FL | ✓ | 53 | Noise | ✓ | 53 | Noise | ✓ | | | | | | | | | |
| 23 | Window Opener FR | ✓ | 54 | Starter Motor | ✓ | 54 | Starter Motor | ✓ | | | | | | | | | |
| 24 | Window Opener RL | ✓ | | | | | | | | | | | | | | | |
| 25 | Window Opener RR | ✓ | | | | | | | | | | | | | | | |
| 26 | Rear View Mirrors | ✓ | | | | | | | | | | | | | | | |
| 27 | Radio (Basic Test Only) | ✓ | | | | | | | | | | | | | | | |
| 28 | CD (Basic Test Only) | ✓ | | | | | | | | | | | | | | | |
| 29 | Boot Open Switch | ✓ | | | | | | | | | | | | | | | |

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

| | | | |
|--|-------------|------------|-------------|
| Inspected by: | Bobby Zhong | Date: | 30 Aug 2019 |
| I have read and understood this condition guide: | | | |
| Name: | | Signature: | |