



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

| | |
|------------|-------------|
| Report ID: | 17,951,663 |
| Version: | 1 |
| Created: | 08 Jul 2019 |

| | | | |
|------------------------------------|--------|-------------|-------------------|
| Make: | Nissan | Body Style: | Hatchback |
| Model: | Juke | VIN: | 7AT0DH8HX19100350 |
| Year: | 2012 | Odometer: | 55,695 Kms |
| Road Conditions During Test Drive: | Dry | | |

| Electrical | | 30 | Fuel Flap Release | ✓ | Cooling System | | 55 | Coolant Condition | ✓ | Exterior | |
|------------|--------------------------|----|------------------------|----------------------------------|----------------|------------------|---------------------------|-------------------|-----|-----------------------------|------|
| 1 | Battery | ✓ | 31 | Reversing Camera | ✓ | 56 | Performance | ✓ | 78 | Under Carriage | Good |
| 2 | Headlights | ✓ | 32 | USB Port | • | 57 | Radiator/Hoses (visual) | ✓ | 79 | Sun Roof Operation | • |
| 3 | Tail Lights | ✓ | 33 | Window Lock Switch | ✓ | Suspension | | | 80 | Front Windscreen (no chips) | Good |
| 4 | High Stop Light | ✓ | Transmission and Drive | | | 58 | Suspension Performance | ✓ | 81 | Back Windscreen (no chips) | Good |
| 5 | Front Right Indicators | ✓ | 34 | Operation | ✓ | 59 | Steering Performance | ✓ | 82 | Side Windows (no chips) | Good |
| 6 | Front Left Indicators | ✓ | 35 | Noise | ✓ | 60 | Shock Absorbers | ✓ | 83 | Front Wiper Blades | Good |
| 7 | Rear Right Indicators | ✓ | 36 | Clutch | • | Wheels and Tyres | | | 84 | Rear Wiper Blade | Good |
| 8 | Rear Left Indicators | ✓ | 37 | CV Joints | ✓ | 61 | Left Front | 5 | 85 | R/H Mirror | Good |
| 9 | Reversing Lights | ✓ | 38 | Wheel Bearing | ✓ | 62 | Right Front | 5 | 86 | L/H Mirror | Good |
| 10 | Rear Reflectors | ✓ | 39 | Wheel Balance | ✓ | 63 | Left Rear | 5 | 87 | L/F Guard | Good |
| 11 | Hazard Lights | ✓ | 40 | Gearbox (Manual) | • | 64 | Right Rear | 5 | 88 | R/F Guard | Good |
| 12 | Courtesy Lights | ✓ | 41 | Engine Timing | Timing Chain | 65 | Spare | Yes | 89 | L/H Doors | Good |
| 13 | Dashboard Lights | ✓ | 42 | Evidence of Cam Belt Replacement | Not Applicable | 66 | Tools | ✓ | 90 | R/H Doors | Good |
| 14 | Dashboard Dimmer Switch | ✓ | 43 | Replaced at (odometer reading) | | Interior | | | 91 | L/H Sill | Good |
| 15 | Number Plate Light | ✓ | Brakes | | | 67 | AC Operation | ✓ | 92 | R/H Sill | Good |
| 16 | Dashboard Warning Lights | ✓ | 44 | Front Brakes | ✓ | 68 | Heater Fan | ✓ | 93 | Boot/Tail Gate | Good |
| 17 | Speedo | ✓ | 45 | Rear Brakes | ✓ | 69 | Seatbelts | ✓ | 94 | Front Bumper | Good |
| 18 | Odometer | ✓ | 46 | Handbrake | ✓ | 70 | Horn | ✓ | 95 | Rear Bumper | Good |
| 19 | Rev Counter | ✓ | Keys and Locking | | | 71 | Seat Heaters | • | 96 | Roof | Good |
| 20 | Fuel Gauge | ✓ | 47 | Central Locking | ✓ | 72 | Sun Visors | ✓ | 97 | Bonnet | Good |
| 21 | Wipers Front/Rear | ✓ | 48 | Remote Locking | ✓ | 73 | Sun Visors Lights/Mirrors | ✓ | 98 | Fuel Cap | ✓ |
| 22 | Window Opener FL | ✓ | 49 | Number of Keys | 1 | 74 | Seats | Good | 99 | Mud Flaps | ✓ |
| 23 | Window Opener FR | ✓ | Engine | | | 75 | Carpets | Good | 100 | WOF | ✓ |
| 24 | Window Opener RL | ✓ | 50 | Oil Level | ✓ | 76 | Panels | Good | | | |
| 25 | Window Opener RR | ✓ | 51 | Smokes and Fumes | ✓ | 77 | Dashboard | Good | | | |
| 26 | Rear View Mirrors | ✓ | 52 | Performance | ✓ | | | | | | |
| 27 | Radio (Basic Test Only) | ✓ | 53 | Noise | ✓ | | | | | | |
| 28 | CD (Basic Test Only) | ✓ | 54 | Starter Motor | ✓ | | | | | | |
| 29 | Boot Open Switch | ✓ | | | | | | | | | |

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

| | | | |
|--|--------------|------------|-------------|
| Inspected by: | Daryll Timms | Date: | 08 Jul 2019 |
| I have read and understood this condition guide: | | | |
| Name: | | Signature: | |