

Report ID: 17,951,745 Version: 4 30 Jul 2019 Created:

| Make: | Ford | Model: | Focus | Body Style: | Hatchback | | Pass | Fail | N/A |
|--|--------------------------|----------------------|------------------------|--------------------|--|-----------------------------|------|--------------|-----|
| Year: | 2004 | Registration: | FLW648 | Reg Expiry: | 15 Jul 2019 | Engine | | | |
| WoF Expiry: | 26 Jul 2020 | Odometer: | 141,299 Kms | Good No: | 17951745 | Oil level | ~ | | |
| VIN: | WF0AXXGCDA2G5257 | Next Service: | 146420 | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | eration is made | for age and mileage | Parts have not | been dismantled or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and th | nis can be arranged fo | r an additional c | harge. | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | SC W | -0 | | - | SD | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent R = rust W D D W W | | | | | | Operation | ~ | | |
| R = rust PT = paint def | | | | \int | JHIH | Noise | ~ | | |
| C = crack | | | | | SC | Clutch | ~ | | |
| P = pin dent | | | | | | CV joints | ~ | | |
| * = decals | sc 916 | | | The | ELIP SD | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs SC W S | | | | | | Performance | ~ | | |
| | | Notocom | defects & blemisbes | | | Hand Brake | | | |
| Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram | | | | | | | | ~ f t | |
| | | | | | Tyres (lowest observed tread depth of tyres) | | | | |
| | | | | | | Left front | | .0 | mm |
| | | | | | | Right front | | .0 | mm |
| r | | | | | | Left rear | 5 | .0 | mm |
| Conditions During Body Inspection: Wet | | | | | | - | | | mm |
| Under Comit on Alle der Deurset laurentien Commente | | | | | | Spare Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | 1 | 1 | |
| engine oil l | eaks | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| Correcto | Good | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| | Good | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | ra | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General C | <u>Comments</u> | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 1 | 1 | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | V | | |
| | | | | | | Remote locking | | ~ | |
| Engine Ti | ming Mechanism: | Cambelt | t | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: Y | es | Kms: 13 | 2,446 | Reversing camera | | | ~ |
| | - | | | | | | | | L * |
| Inspected by: Brian Hill Date: 10 Jul 2019 | | | | | | | | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: