

## **Basic Vehicle Condition Guide**

Report ID: 17,952,240


Version: 5

Created: 22 Jul 2019

Make: Model: Mitsubishi L300 **Body Style:** Van Year: 2014 Registration: HLH748 Reg Expiry: 04 Aug 2019 WoF Expiry: **Odometer:** 30 May 2020 43,713 Kms **Good No:** 17952240 VIN: JMAHNP14VDA80092 **Next Service:** 44300 Service History:

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

RR lens cracked. Chip in screen R side door stiff to open

**Conditions During Body Inspection:** 

**Under Carriage & Under Bonnet Inspection Comments** 

Dirty

Interior Comments			
Seats	stains		
Carpets	holes		
Panels	scratches. scuffs. dents		
Dashboard	Poor		

## **General Comments**

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism: Timing Chain** 

**Evidence of Cam Belt Replacement:** Not Applicable Kms:

Stuart Melbourne Inspected by:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	<i>'</i>		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission		•	•
Operation	~		
Noise	~		
Clutch	~		
CV joints			~
Wheel bearings	~		
Brakes			•
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	5	.7	mm
Right front	5.3		mm
Left rear	5.7		mm
Right rear	6.1		mm
Spare	Yes		
Suspension	1		
Suspension performance	~		
Steering performance	V		
Shock absorbers	~		
Air Conditioning / Heater	1		
Operation			~
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL			~
Window winder FR			~
Window winder RL			~
Window winder RR			~
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)			~
Number of keys	1		
Central locking	·		
Remote locking			_
Sat. Nav. (basic test only)			-
Reversing camera			~
	I	l	1 -

I have read and understood this condition guide.

Name: .....

Signature: .....

11 Jul 2019

Date: