

Basic Vehicle Condition Guide

Report ID: 17,952,422


Version: 4

Created: 29 Aug 2019

Make: Model: Toyota Landcruiser **Body Style:** SUV Year: 2004 Registration: **GFE846** Reg Expiry: 29 Aug 2019 WoF Expiry: **Odometer:** 06 Aug 2020 246,184 Kms **Good No:** 17952422 VIN: 7AT0H60HX10151300 **Next Service:** 247,989kms Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

F/L indicator lens chipped. Holes on roof, filled.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

OK.

Interior Comm	<u>nents</u>
Seats	very dirty. middle head rest is missing
Carpets	very dirty.
Panels	very dirty.
Dashboard	Average

General Comments

Inspected by:

Tough 8 seater 4WD Landcruiser. Cam belt due at 250000

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Daryll Timms

Evidence of Cam Belt Replacement: Yes Kms:

Kms: 100,386

	_	F 11	N1/A	
	Pass	Fail	N/A	
Engine				
Oil level	'			
Smoke & fumes	<i>\</i>			
Performance	~			
Noise	•			
Cooling System				
Coolant condition	V			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission		1		
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread depth of tyres)				
Left front	8	.0	mm	
Right front	8	.0	mm	
Left rear	9	.0	mm	
Right rear	9.0		mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater				
Operation 🗸				
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	<i>y</i>			
Wipers (front & rear)	~			
Window winder FL	~			
Window winder FR	<i>'</i>			
Window winder RL	•			
Window winder RR	•			
Rear view mirrors	V V V V V			
Radio (basic test only)	V			
CD (basic test only)		./	-	
Number of keys	1		L	
·	1		1	
Central locking	•		-	
Remote locking				
Sat. Nav. (basic test only)			'	
Reversing camera			-	

I have read and understood this condition guide.

Name:

Signature:

12 Jul 2019

Date: