

Basic Vehicle Condition Guide

Report ID: 17,953,088


Version:

Created: 10 Oct 2019

Make: Model: Hyundai lload **Body Style:** Van Year: 2014 Registration: HQQ91 Reg Expiry: 08 Sep 2019 WoF Expiry: **Odometer: Good No:** 18 Sep 2020 89,684 Kms 17953088 VIN: KMFWBX7KLEU62969 **Next Service:** 97200 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Tailgate rubber torn. Tailgate trim damaged. Left parklight not working

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Interior Comments	<u>S</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

	_
General	Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

	11		•						
		Sat. Nav. (basic test only)			~				
Kms:		Reversing camera	~						
Date: 23 Sep 2019									
Name:		Signature:							

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	~		
Noise	~		1
Cooling System			
Coolant condition	~		
Performance	~		+
Radiator / Hoses (visual)	~		+
Transmission			
Operation	V		T
Noise	~		
Clutch	~		+
CV joints			-
Wheel bearings			+
Brakes	V		
Performance			Τ
	-		
Hand Brake		۲.	
Tyres (lowest observed tread			
Left front	7	.0	mm
Right front	4.0		mm
Left rear	2.0		mm
Right rear	2	.0	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL			~
Window winder RR			~
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		1
Sat. Nav. (basic test only)			·
Reversing camera	~		Ť
coming currieru		1	4

I have read and understood this condition guide.