



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

| | |
|------------|-------------|
| Report ID: | 17,953,878 |
| Version: | 1 |
| Created: | 25 Jul 2019 |

| | | | |
|------------------------------------|--------|-------------|-------------------|
| Make: | Nissan | Body Style: | Hatchback |
| Model: | Note | VIN: | 7AT0DH79X19381459 |
| Year: | 2009 | Odometer: | 44,488 Kms |
| Road Conditions During Test Drive: | Dry | | |

| Electrical | | 30 | Fuel Flap Release | ✓ | Cooling System | | 55 | Coolant Condition | ✓ | Exterior | | 78 | Under Carriage | Good |
|------------|--------------------------|----|------------------------|----------------------------------|----------------|-----------------|-------------------------|-------------------|------------------------|----------------------------|------------|--------------------|-----------------------------|------|
| 1 | Battery | ✓ | 31 | Reversing Camera | • | 56 | Performance | ✓ | 79 | Sun Roof Operation | • | 80 | Front Windscreen (no chips) | Good |
| 2 | Headlights | ✓ | 32 | USB Port | • | 57 | Radiator/Hoses (visual) | ✓ | 81 | Back Windscreen (no chips) | Good | 82 | Side Windows (no chips) | Good |
| 3 | Tail Lights | ✓ | 33 | Window Lock Switch | ✓ | Suspension | | 58 | Suspension Performance | ✓ | 83 | Front Wiper Blades | Good | |
| 4 | High Stop Light | ✓ | Transmission and Drive | | 34 | Operation | ✓ | 59 | Steering Performance | ✓ | 84 | Rear Wiper Blade | Good | |
| 5 | Front Right Indicators | ✓ | 35 | Noise | ✓ | 60 | Shock Absorbers | ✓ | Wheels and Tyres | | 85 | R/H Mirror | Good | |
| 6 | Front Left Indicators | ✓ | 36 | Clutch | • | 61 | Left Front | 7 | mm | 86 | L/H Mirror | Good | | |
| 7 | Rear Right Indicators | ✓ | 37 | CV Joints | ✓ | 62 | Right Front | 7 | mm | 87 | L/F Guard | Good | | |
| 8 | Rear Left Indicators | ✓ | 38 | Wheel Bearing | ✓ | 63 | Left Rear | 7 | mm | 88 | R/F Guard | Good | | |
| 9 | Reversing Lights | ✓ | 39 | Wheel Balance | ✓ | 64 | Right Rear | 7 | mm | 89 | L/H Doors | Good | | |
| 10 | Rear Reflectors | ✓ | 40 | Gearbox (Manual) | • | 65 | Spare | Yes | 90 | R/H Doors | Good | | | |
| 11 | Hazard Lights | ✓ | 41 | Engine Timing | Timing Chain | 66 | Tools | ✓ | 91 | L/H Sill | Good | | | |
| 12 | Courtesy Lights | ✓ | 42 | Evidence of Cam Belt Replacement | Not Applicable | Interior | | 67 | AC Operation | ✓ | 92 | R/H Sill | Good | |
| 13 | Dashboard Lights | ✓ | 43 | Replaced at (odometer reading) | | 68 | Heater Fan | ✓ | 93 | Boot/Tail Gate | Good | | | |
| 14 | Dashboard Dimmer Switch | • | Brakes | | 44 | Front Brakes | ✓ | 69 | Seatbelts | ✓ | 94 | Front Bumper | Good | |
| 15 | Number Plate Light | ✓ | 45 | Rear Brakes | ✓ | 70 | Horn | ✓ | 95 | Rear Bumper | Good | | | |
| 16 | Dashboard Warning Lights | ✓ | 46 | Handbrake | ✓ | 71 | Seat Heaters | • | 96 | Roof | Good | | | |
| 17 | Speedo | ✓ | Keys and Locking | | 47 | Central Locking | ✓ | 72 | Sun Visors | ✓ | 97 | Bonnet | Good | |
| 18 | Odometer | ✓ | 48 | Remote Locking | • | 49 | Number of Keys | 1 | 73 | Sun Visors Lights/Mirrors | ✓ | 98 | Fuel Cap | ✓ |
| 19 | Rev Counter | ✓ | Engine | | 50 | Oil Level | ✓ | 74 | Seats | Good | 99 | Mud Flaps | ✓ | |
| 20 | Fuel Gauge | ✓ | 51 | Smokes and Fumes | ✓ | 52 | Performance | ✓ | 75 | Carpets | Good | 100 | WOF | ✓ |
| 21 | Wipers Front/Rear | ✓ | 53 | Noise | ✓ | 54 | Starter Motor | ✓ | 76 | Panels | Good | | | |
| 22 | Window Opener FL | ✓ | | | | | | | 77 | Dashboard | Good | | | |
| 23 | Window Opener FR | ✓ | | | | | | | | | | | | |
| 24 | Window Opener RL | ✓ | | | | | | | | | | | | |
| 25 | Window Opener RR | ✓ | | | | | | | | | | | | |
| 26 | Rear View Mirrors | ✓ | | | | | | | | | | | | |
| 27 | Radio (Basic Test Only) | ✓ | | | | | | | | | | | | |
| 28 | CD (Basic Test Only) | ✓ | | | | | | | | | | | | |
| 29 | Boot Open Switch | ✓ | | | | | | | | | | | | |

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

| | | | |
|---------------|--------------|-------|-------------|
| Inspected by: | Daryll Timms | Date: | 25 Jul 2019 |
|---------------|--------------|-------|-------------|

I have read and understood this condition guide:

| | | | |
|-------|--|------------|--|
| Name: | | Signature: | |
|-------|--|------------|--|