



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

| | |
|------------|-------------|
| Report ID: | 17,953,897 |
| Version: | 1 |
| Created: | 25 Jul 2019 |

| | | | |
|------------------------------------|----------|-------------|-------------------|
| Make: | Nissan | Body Style: | Wagon |
| Model: | Wingroad | VIN: | 7AT0DH5GX19092265 |
| Year: | 2008 | Odometer: | 87,269 Kms |
| Road Conditions During Test Drive: | Dry | | |

| Electrical | | 30 | Fuel Flap Release | ✓ | Cooling System | | 55 | Coolant Condition | ✓ | Exterior | | 78 | Under Carriage | Good | | | |
|------------|--------------------------|----|------------------------|----------------------------------|----------------|------------------|---------------------------|-------------------------------------|----------------------------|----------------------------|------------|--------------------|-----------------------------|-----------|------------------|--------------|------|
| 1 | Battery | ✓ | 31 | Reversing Camera | • | 56 | Performance | ✓ | 79 | Sun Roof Operation | • | 80 | Front Windscreen (no chips) | Good | | | |
| 2 | Headlights | ✓ | 32 | USB Port | • | 57 | Radiator/Hoses (visual) | ✓ | 81 | Back Windscreen (no chips) | Good | 82 | Side Windows (no chips) | Good | | | |
| 3 | Tail Lights | ✓ | 33 | Window Lock Switch | ✓ | Suspension | | 58 | Suspension Performance | ✓ | 83 | Front Wiper Blades | Good | 84 | Rear Wiper Blade | Good | |
| 4 | High Stop Light | ✓ | Transmission and Drive | | 34 | Operation | ✓ | 59 | Steering Performance | ✓ | 85 | R/H Mirror | Good | 86 | L/H Mirror | Good | |
| 5 | Front Right Indicators | ✓ | 35 | Noise | ✓ | 60 | Shock Absorbers | ✓ | 61 | Left Front | 3 | mm | 87 | L/F Guard | Good | | |
| 6 | Front Left Indicators | ✓ | 36 | Clutch | • | Wheels and Tyres | | 62 | Right Front | 2 | mm | 88 | R/F Guard | Good | 89 | L/H Doors | Good |
| 7 | Rear Right Indicators | ✓ | 37 | CV Joints | ✓ | 63 | Left Rear | 2 | mm | 64 | Right Rear | 2 | mm | 90 | R/H Doors | Good | |
| 8 | Rear Left Indicators | ✓ | 38 | Wheel Bearing | ✓ | 65 | Spare | Yes | 66 | Tools | ✓ | 91 | L/H Sill | Good | 92 | R/H Sill | Good |
| 9 | Reversing Lights | ✓ | 39 | Wheel Balance | ✓ | 67 | AC Operation | ✓ | 68 | Heater Fan | ✓ | 93 | Boot/Tail Gate | Good | 94 | Front Bumper | Good |
| 10 | Rear Reflectors | ✓ | 40 | Gearbox (Manual) | • | 69 | Seatbelts | ✓ | 70 | Horn | ✓ | 95 | Rear Bumper | Good | 96 | Roof | Good |
| 11 | Hazard Lights | ✓ | 41 | Engine Timing | Timing Chain | 71 | Seat Heaters | • | 72 | Sun Visors | ✓ | 97 | Bonnet | Good | 98 | Fuel Cap | ✓ |
| 12 | Courtesy Lights | ✓ | 42 | Evidence of Cam Belt Replacement | Not Applicable | 73 | Sun Visors Lights/Mirrors | ✓ | 74 | Seats | Good | 99 | Mud Flaps | ✓ | 100 | WOF | ✓ |
| 13 | Dashboard Lights | ✓ | 43 | Replaced at (odometer reading) | | Interior | | 75 | Carpets | Good | 76 | Panels | Good | 77 | Dashboard | Good | |
| 14 | Dashboard Dimmer Switch | • | 44 | Front Brakes | ✓ | 77 | Dashboard | Good | Turners Certification Key: | | | | | | | | |
| 15 | Number Plate Light | ✓ | 45 | Rear Brakes | ✓ | ✓ = Pass | | | | | | | | | | | |
| 16 | Dashboard Warning Lights | ✓ | 46 | Handbrake | ✓ | ✗ = Fail | | | | | | | | | | | |
| 17 | Speedo | ✓ | Keys and Locking | | 47 | Central Locking | ✓ | • = Not applicable for this vehicle | | | | | | | | | |
| 18 | Odometer | ✓ | 48 | Remote Locking | ✓ | 49 | Number of Keys | 2 | | | | | | | | | |
| 19 | Rev Counter | ✓ | Engine | | 50 | Oil Level | ✓ | | | | | | | | | | |
| 20 | Fuel Gauge | ✓ | 51 | Smokes and Fumes | ✓ | 52 | Performance | ✓ | | | | | | | | | |
| 21 | Wipers Front/Rear | ✓ | 53 | Noise | ✓ | 54 | Starter Motor | ✓ | | | | | | | | | |
| 22 | Window Opener FL | ✓ | | | | | | | | | | | | | | | |
| 23 | Window Opener FR | ✓ | | | | | | | | | | | | | | | |
| 24 | Window Opener RL | ✓ | | | | | | | | | | | | | | | |
| 25 | Window Opener RR | ✓ | | | | | | | | | | | | | | | |
| 26 | Rear View Mirrors | ✓ | | | | | | | | | | | | | | | |
| 27 | Radio (Basic Test Only) | ✓ | | | | | | | | | | | | | | | |
| 28 | CD (Basic Test Only) | ✓ | | | | | | | | | | | | | | | |
| 29 | Boot Open Switch | ✓ | | | | | | | | | | | | | | | |

| | | | |
|---------------|--------------|-------|-------------|
| Inspected by: | Daryll Timms | Date: | 25 Jul 2019 |
|---------------|--------------|-------|-------------|

I have read and understood this condition guide:

| | | | |
|-------|--|------------|--|
| Name: | | Signature: | |
|-------|--|------------|--|