

Report ID: 17,954,888 Version: 3 10 Sep 2019 Created:

Make:	lsuzu	Model:	D-MAX	Body Style:	Utility		Pass	Fail	N/A
Year:	2016	<b>Registration:</b>	JWZ208	Reg Expiry:	29 Jun 2020	Engine	I	<u> </u>	L
WoF Expiry:		Odometer:	86,625 Kms	Good No:	17954888	Oil level	~		
VIN:	MPATFR85JGT000955	Next Service:	91000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and t	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
	SC		S PT SC S D		SC	Performance	~		
Key:				500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	sc			20		Operation	~		
PT = paint def	ect NP				11111	Noise	~		
C = crack						Clutch	~		
P = pin dent	sc				2416	CV joints			~
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	S P		S SC		SC	Performance	~		
Body Inst	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Screen chips						Tyres (lowest observed tread depth of tyres)			
						Left front	8	.5	mm
						Right front	8	3	mm
						Left rear	4	.5	mm
Conditions During Body Inspection: Dry						Right rear	8 mi		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Clean						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Interior Comments Average						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	Good Good					Wipers (front & rear)	~		
						Window winder FL	~		
Concret	<u>Comments</u>					Window winder FR	~		
						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
Engine Ti	ming Mechanism:	Unknow	/n			Remote locking	~		
						Sat. Nav. (basic test only)			~
			lot Applicable	11115.		Reversing camera	~		
Inspected by: Donovan Matara Date: 10 Sep 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....