

Report ID: 17,955,411 Version: 1 07 Aug 2019 Created:

Make:	Mitsubishi	Model:	Triton	Body Style:	Utility		Pass	Fail	N/A
Year:	2015	<b>Registration:</b>	JCQ561	Reg Expiry:	24 Aug 2019	Engine	1		
WoF Expiry:	25 May 2020	Odometer:	109,760 Kms	Good No:	17955411	Oil level	~		
VIN:	MMAJYKL10GH00062	Next Service:	117500	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
			S S			Performance	~		
Key:		-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	SC A			710	HIVS	Operation	~		
PT = paint def	ect NP				17111	Noise	~		
C = crack						Clutch			~
P = pin dent	sc				74116	CV joints	~		
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	S				S	Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishe	s may not be disp	played in the diagram	Hand Brake	~		
Scratches L c pillar						Tyres (lowest observed tread depth of tyres)			
						Left front	5.5 mm		mm
						Right front	5.	5	mm
						Left rear	5	5	mm
Conditions During Body Inspection:						Right rear	5 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Tidy						Suspension performance	~		
						Steering performance	~		
Shock absorbers							~		
	Air Conditioning / Heater								
Operatio							~		
Interior Comments						Electrical / Accessories			
Seats	RF hole					Head lights	~		
Carpote	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
Dastibua						Window winder FL	~		
						Window winder FR	~		
General Comments Surge in revs at idle						Window winder RL	~		
Surge in rev	is at idle					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry Central locking									
Г		<del></del>				Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Stuart Melbourne Date: 07 Aug 2019									
Inspected by. Stdart Melbourne Date: 07 Aug 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....