

Basic Vehicle Condition Guide

Report ID: 17,956,109


Version: 1

Created: 20 Jun 2019

Make: Model: **Body Style:** SUV Hyundai Santa FE Year: 2016 Registration: JPS331 Reg Expiry: 22 May 2019 WoF Expiry: **Odometer: Good No:** 22 Feb 2020 195,836 Kms 17956109 VIN: KMHST81XSGU61291! **Next Service:** Service History: Yes 199600

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

Dirty

Lower grille damaged

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Average		
Dashboard	Good		

Wet

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Stuart Melbourne

Create	a: 20	Jun 20	J19		
	Pass	Fail	N/A		
Engine					
Oil level	~				
Smoke & fumes	\(\times \)				
Performance	~				
Noise	~				
Cooling System					
Coolant condition	~				
Performance	V				
Radiator / Hoses (visual)	~				
Transmission					
Operation	~				
Noise	~				
Clutch			~		
CV joints	~				
Wheel bearings	~				
Brakes					
Performance	~				
Hand Brake	~				
Tyres (lowest observed treac	d depth	of tyre	!s)		
Left front	I		mm		
Right front	7.4		mm		
Left rear	-		mm		
Right rear	6.2		mm		
Spare		Yes			
Suspension					
Suspension performance	~				
Steering performance	~				
Shock absorbers	~				
Air Conditioning / Heater			l		
Operation 🗸					
Electrical / Accessories					
Head lights	V				
Tail lights	~				
Indicators	~				
Dashboard warning lights	~				
Wipers (front & rear)	~				
Window winder FL	~				
Window winder FR	~				
Window winder RL	~				
Window winder RR	V V V V V V				
Rear view mirrors	~				
Radio (basic test only)	~				
CD (basic test only)	~				
Number of keys	2	L	<u> </u>		
Central locking	<i>V</i>				
Remote locking	~				
Sat. Nav. (basic test only)			~		
Reversing camera	~				
<u> </u>	1	İ	I		

20 Jun 2019

Date:

have read and understood this condition guide.	Name:	Signature: