



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	17,956,236
Version:	3
Created:	13 Sep 2019

Make:	Subaru	Body Style:	Wagon
Model:	Legacy	VIN:	7AT0GF0BX19019156
Year:	2010	Odometer:	127,441 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good			
1	Battery	✓	31	Reversing Camera	•	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good			
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good			
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓	83	Front Wiper Blades	Good	84	Rear Wiper Blade	Good	
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓	59	Steering Performance	✓	85	R/H Mirror	Good	86	L/H Mirror	Good	
5	Front Right Indicators	✓	35	Noise	✓	60	Shock Absorbers	✓	Wheels and Tyres		87	L/F Guard	Good	88	R/F Guard	Good	
6	Front Left Indicators	✓	36	Clutch	•	61	Left Front	7	mm	62	Right Front	7	mm	89	L/H Doors	Good	
7	Rear Right Indicators	✓	37	CV Joints	✓	63	Left Rear	7	mm	64	Right Rear	7	mm	90	R/H Doors	Good	
8	Rear Left Indicators	✓	38	Wheel Bearing	✓	65	Spare	Yes	66	Tools	✓	91	L/H Sill	Good	92	R/H Sill	Good
9	Reversing Lights	✓	39	Wheel Balance	✓	Interior		67	AC Operation	✓	93	Boot/Tail Gate	Good	94	Front Bumper	Good	
10	Rear Reflectors	✓	40	Gearbox (Manual)	•	68	Heater Fan	✓	69	Seatbelts	✓	95	Rear Bumper	Good	96	Roof	Good
11	Hazard Lights	✓	41	Engine Timing	Cambelt	70	Horn	✓	71	Seat Heaters	•	97	Bonnet	Good	98	Fuel Cap	✓
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Yes	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	99	Mud Flaps	✓	100	WOF	✓
13	Dashboard Lights	✓	43	Replaced at (odometer reading)	100,000	74	Seats	Good	75	Carpets	Good						
14	Dashboard Dimmer Switch	✓	Brakes		44	Front Brakes	✓	76	Panels	Good	77	Dashboard	Good				
15	Number Plate Light	✓	45	Rear Brakes	✓	Keys and Locking		77									
16	Dashboard Warning Lights	✓	46	Handbrake	✓	47	Central Locking	✓									
17	Speedo	✓			48	Remote Locking	✓										
18	Odometer	✓	Keys and Locking		49	Number of Keys	2										
19	Rev Counter	✓			Engine		50	Oil Level	✓								
20	Fuel Gauge	✓	51	Smokes and Fumes	✓	52	Performance	✓									
21	Wipers Front/Rear	✓	53	Noise	✓	54	Starter Motor	✓									
22	Window Opener FL	✓															
23	Window Opener FR	✓															
24	Window Opener RL	✓															
25	Window Opener RR	✓															
26	Rear View Mirrors	✓															
27	Radio (Basic Test Only)	✓															
28	CD (Basic Test Only)	✓															
29	Boot Open Switch	✓															

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Daryll Timms	Date:	13 Sep 2019
---------------	--------------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--