

Report ID: 17,957,170


Version: 1

Created: 28 Mar 2019

Make:	BMW	Model:	1	Body Style:	Hatchback
Year:	2017	Registration:	LBH526	Reg Expiry:	29 Nov 2019
WoF Expiry:		Odometer:	4,922 Kms	Good No:	17957170
VIN:	WBY1Z62010V989308	Next Service:		Service History	/: No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Tidy

Interior Comments					
Seats	Good				
Carpets	Good				
Panels	Good				
Dashboard	Good				

_	_
Conoral	Comments
General	COMMENTS

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Unknown

Evidence of Cam Belt Replacement: Not Applicable Kms:

Stuart Melbourne 28 Mar 2019 Inspected by: Date:

Name:

	Pass	Fail	N/A
Engine			
Oil level			~
Smoke & fumes			~
Performance			~
Noise			~
Cooling System			
Coolant condition			~
Performance			~
Radiator / Hoses (visual)			~
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings			~
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed treac	depth	of tyre	es)
Left front	į	5	mm
Right front	į	5	mm
Left rear	į	5	mm
Right rear	į	5	mm
Spare		No	
Suspension			
Suspension performance	V V		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	\(\times \)		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL			~
Window winder RR			~
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)			~
Number of keys	2		
Central locking	~		
Remote locking	-		
Sat. Nav. (basic test only)	~		
Reversing camera	′		

Signature: