

Report ID: 17,957,714 Version: 1 10 Apr 2019 Created:

| Make:  | Hyundai                | Model:          | lx35                   | Body Style:                     | SUV                  |                              | Pass    | Fail    | N/A     |
|--|------------------------|-----------------|------------------------|---------------------------------|----------------------|------------------------------|---------|---------|---------|
| Year:  | 2015                   | Registration:   | HYP352                 | Reg Expiry:                     | 09 May 2019          | Engine                       |         |         | L       |
| WoF Expiry:  | 10 Feb 2020            | Odometer:       | 148,761 Kms            | Good No:                        | 17957714             | Oil level                    | ~       |         |         |
| VIN:   | KMHJU81GSFU05993(      | Next Service:   | 161972                 | Service History                 | <b>y:</b> Yes        | Smoke & fumes                | ~       |         |         |
|  |                        |                 |                        |                                 |                      | Performance                  | ~       |         |         |
|  | port is not a warranty | unting is goods | for one and miles as   | Danta hava nat                  | heen discontined or  | Noise                        | ~       |         |         |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. |                        |                 |                        |                                 |                      | Cooling System               |         |         |         |
|  |                        |                 |                        |                                 |                      | Coolant condition            |         |         |         |
|  |                        |                 |                        |                                 |                      | Performance                  | ~       |         |         |
| Key:   |                        | -0              | S S                    |                                 | s                    | Radiator / Hoses (visual)    | ~       |         |         |
| S = scratch  | ATE.                   |                 |                        | NG G                            | <u>که</u>            | Transmission                 |         |         | L       |
| D = dent<br>R = rust   | SC DE                  |                 |                        | 715                             | HILS                 | Operation                    | ~       |         |         |
| R = rust<br>PT = paint defe  |                        |                 |                        | $\left[ \right] \left[ \right]$ |                      | Noise                        | ~       |         |         |
| C = crack  |                        |                 |                        |                                 | D                    | Clutch                       |         |         | ~       |
| P = pin dent   | HID                    |                 |                        |                                 | 74114                | CV joints                    | ~       |         |         |
| * = decals   | SPSC 916               |                 |                        | The                             |                      | Wheel bearings               | ~       |         |         |
| SC = stone chips   |                        |                 |                        |                                 |                      | Brakes                       |         |         |         |
| W = significant  | t scuffs W             |                 | S S                    |                                 | S                    | Performance                  | ~       |         |         |
| Podulaca   | Dection Comments       | Note: som       | ne defects & blemishes | may not be disp                 | layed in the diagram | Hand Brake                   | ~       |         |         |
|  |                        |                 |                        |                                 |                      | Tyres (lowest observed tread | d depth | of tyre | L<br>S) |
|  |                        |                 |                        |                                 |                      | Left front                   | 6       |         | mm      |
|  |                        |                 |                        |                                 |                      | Right front                  | 6       |         | mm      |
|  |                        |                 |                        |                                 |                      | Left rear                    | 6       |         | mm      |
| Conditions During Body Inspection: Dry   |                        |                 |                        |                                 |                      | Right rear                   | 6 mm    |         | mm      |
|  |                        |                 |                        |                                 |                      | Spare                        | Yes     |         |         |
| Under Carriage & Under Bonnet Inspection Comments  |                        |                 |                        |                                 |                      | Suspension                   |         |         |         |
| Dirty  |                        |                 |                        |                                 |                      | Suspension performance       | ~       |         |         |
|  |                        |                 |                        |                                 |                      | Steering performance         | ~       |         |         |
|  |                        |                 |                        |                                 |                      | Shock absorbers              | ~       |         |         |
|  |                        |                 |                        |                                 |                      | Air Conditioning / Heater    |         |         |         |
|  |                        |                 |                        |                                 |                      | Operation                    | ~       |         |         |
| Interior Comments  |                        |                 |                        |                                 |                      | Electrical / Accessories     |         |         |         |
| Seats  | RF holes               |                 |                        |                                 |                      | Head lights                  | ~       |         |         |
|  | Good                   |                 |                        |                                 |                      | Tail lights                  | ~       |         |         |
| Carpets  |                        |                 |                        |                                 |                      | Indicators                   | ~       |         |         |
| Panels   | Good                   |                 |                        |                                 |                      | Dashboard warning lights     | ~       |         |         |
|  | , Good                 |                 |                        |                                 |                      | Wipers (front & rear)        | ~       |         |         |
| Dashboa  | rd                     |                 |                        |                                 |                      | Window winder FL             | ~       |         |         |
|  |                        |                 |                        |                                 |                      | Window winder FR             | ~       |         |         |
| <u>General C</u>   | <u>Comments</u>        |                 |                        |                                 |                      | Window winder RL             | ~       |         |         |
|  |                        |                 |                        |                                 |                      | Window winder RR             | ~       |         |         |
|  |                        |                 |                        |                                 |                      | Rear view mirrors            | ~       |         |         |
|  |                        |                 |                        |                                 |                      | Radio (basic test only)      | ~       |         |         |
|  |                        |                 |                        |                                 |                      | CD (basic test only)         | ~       |         |         |
|  |                        |                 |                        |                                 |                      | Number of keys               | 1       |         |         |
| Road Conditions During Test Drive: Dry Central locking   |                        |                 |                        |                                 |                      |                              | ~       |         |         |
|  |                        |                 |                        |                                 |                      | Remote locking               | ~       |         |         |
| •  | ming Mechanism:        | Timing (        |                        |                                 |                      | Sat. Nav. (basic test only)  |         |         | ~       |
| Evidence   | of Cam Belt Replac     | ement: N        | lot Applicable         | Kms:                            |                      | Reversing camera             | ~       |         |         |
| Inspected by: Stuart Melbourne Date: 10 Apr 2019   |                        |                 |                        |                                 |                      |                              |         |         |         |

I have read and understood this condition guide.

Name: .....

Signature: .....