



# Turners Certified Imports 50 Point Check

Report ID: 17,957,780

Version: 1

Created: 29 Mar 2019

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make: Body Style:  
Model: Odometer: 90,332 Kms  
Year: VIN: 7AT0CJ3MX19011496

### Under Carriage & Under Bonnet Inspection Comments

Tidy.

### General Comments

Quiet, smooth AWD SUV.

Seats: Good

Carpets: Good

Panels: Good

Dashboard: Good

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable

Replaced At (odometer reading):

Road Conditions During Test Drive: Dry

### Electrical

Battery ☒  
Head lights ☒  
Tail lights ☒  
Indicators ☒  
Dashboard warning lights ☒  
Wipers (front & rear) ☒  
Window winder FL ☒  
Window winder FR ☒  
Window winder RL ☒  
Window winder RR ☒  
Rear view mirrors ☒  
Radio (basic test only) ☒  
CD (basic test only) ☒  
Reversing camera ☒

### Transmission & Drive

Operation ☒  
Noise ☒  
Clutch ☐  
CV joints ☒  
Wheel bearings ☒  
Wheel balance ☒

### Brakes

Performance ☒  
Hand Brake ☒

### Keys & Locking

Central locking ☒  
Remote locking ☒  
Number of keys

### Engine

Oil level ☒  
Smoke & fumes ☒  
Performance ☒  
Noise ☒

### Cooling System

Coolant condition ☒  
Performance ☒  
Radiator / Hoses (visual) ☒

### Suspension

Suspension performance ☒  
Steering performance ☒  
Shock absorbers ☒

### Tyres (lowest observed tread depth)

Left front  mm  
Right front  mm  
Left rear  mm  
Right rear  mm  
Spare   
Tools ☒

### Interior

AC Operation ☒  
Heater fan ☒  
Seatbelts ☒  
Horn ☒

### Turners Certified Key

✓ = Pass X = Fail  
• = Not applicable for this vehicle

Inspected by: Daryll Timms

Date: 29 Mar 2019

I have read and understood this condition guide.

Name: .....

Signature: .....