

Basic Vehicle Condition Guide

Report ID: 17,958,413


Version: 2

Created: 16 Apr 2019

Make: Model: 307 Peugeot **Body Style:** Sports Car Year: 2004 Registration: LLE797 Reg Expiry: 25 May 2019 WoF Expiry: **Odometer: Good No:** 27 Mar 2020 84,103 Kms 17958413 VIN: **Next Service:** VF33BRFNF83495653 88600 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chips front screen.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

	_
General	Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:**

No

Kms:

Inspected by: Brian Hill

Name:

	Pass	Fail	N/A
ngine		1	
Oil level	~		
Smoke & fumes	v		
Performance	~		
Noise	~		
ooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
ransmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
rakes			
Performance	V		
Hand Brake	~		
yres (lowest observed tread	d depth	of tyre	es)
Left front	4	.0	mm
Right front	5	.0	mm
Left rear	6.0		mm
Right rear	6.0		mm
Spare		Yes	
uspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
ir Conditioning / Heater	1		
Operation	~		
ectrical / Accessories			1
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	V V V		
Window winder FR	~		
Window winder RL	~		
Window winder RR			
Rear view mirrors	V V		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys			1
Central locking	1		
Remote locking	~		
Sat. Nav. (basic test only)	+		1
			./
Reversing camera	10		

Signature: