

Report ID: 17,958,466 Version: 1 11 Apr 2019 Created:

Make:	Holden	Model:	Cruze	Body Style:	Hatchback			Pass	Fail	N/A
Year:	2016	Registration:	KDK763	Reg Expiry:	07 Dec 2019	9	Engine	•		·
WoF Expiry:	13 Oct 2019	Odometer:	47,666 Kms	Good No:	17958466		Oil level	~		
VIN:	6G1PD6EMXGL24480	Next Service:	69.000kms	Service Histor	y: Yes		Smoke & fumes	~		
							Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or							Noise	V		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Cooling System			
a full mechan	lical inspection prior to	purchase and t	his can be arranged fo	or an additional c	harge.		Coolant condition	~		
							Performance	~		
Key:		-0	S	\square			Radiator / Hoses (visual)	~		
S = scratch							Transmission			
D = dent R = rust	SC DI			715	HIV		Operation	~		
R = rust PT = paint defe	ect NP			$\left(\left \right\rangle \right)$	JUH		Noise	~		
C = crack				+			Clutch			~
P = pin dent	HID				111		CV joints	~		-
* = decals	sc 916		×	The	HIK		Wheel bearings	~		
SC = stone chips							Brakes			
W = significant scuffs							Performance	~		
		Note: son	ne defects & blemishes	may not be disp	laved in the d	diagram	Hand Brake	~		$\left - \right $
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram								•	oftyre	 (کد
Stone chip on screen.						Tyres (lowest observed tread depth of tyres) Left front 3 mm				
							Right front			mm
							Left rear	4		mm
Conditions During Body Inspection: Wet									mm	
Under Carriage & Under Bonnet Inspection Comments										
Tidy.	inage a onder bor	meenspeede	<u>on comments</u>				Suspension			
nuy.							Suspension performance	~		
							Steering performance	~		
							Shock absorbers	~		
							Air Conditioning / Heater			
Interior Comments							Operation 🖌			
Good							Electrical / Accessories			
Seats	0000						Head lights	~		
Carpets	Average						Tail lights	~		<u> </u>
	Card						Indicators	~		<u> </u>
Panels	Good						Dashboard warning lights	~		
Dashboa	Good						Wipers (front & rear)	~		
							Window winder FL	~		
	_						Window winder FR	~		
General Comments Nice tidy Cruze hatch.							Window winder RL	~		
Nice tidy Cr	uze natch.						Window winder RR	~		
							Rear view mirrors	~		
							Radio (basic test only)	~		
							CD (basic test only)	~		
							Number of keys	2		
Road Conditions During Test Drive: Wet							Central locking	~		
							Remote locking	~		
Engine Timing Mechanism: Timing Chain							Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:							Reversing camera			~
								1	í	I
Inspected by: Daryll Timms Date: 11 Apr 2019										

I have read and understood this condition guide.

Name:

Signature: