

Basic Vehicle Condition Guide

Report ID: 17,959,281

Pass

Version: 1

Engine

Oil level

Created: 10 Apr 2019


Fail

N/A

Make: Mitsubishi Model: Triton **Body Style:** Utility Year: 2012 Registration: GMC32 **Reg Expiry:** 01 Jul 2019 WoF Expiry: **Odometer:** 12 Oct 2019 121,786 Kms **Good No:** 17959281 VIN: MMAJNKA40CD01765 Next Service: 133000 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



body inspection comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Tidy

Interior Comment	<u>'S</u>
Seats	stains
Carpets	Average
Panels	Average
Dashboard	Average

	_
General	Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes

Stuart Melbourne

es Kms: 100,417

Smoke & fumes 1 Performance V Noise / Cooling System Coolant condition Performance Radiator / Hoses (visual) **Transmission** Operation V Noise 1 Clutch / CV joints V Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm Right front 2 mm Left rear mm Right rear 1 mm Spare Yes Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors / Radio (basic test only) ~ CD (basic test only) 1 Number of keys 2 Central locking Remote locking Sat. Nav. (basic test only) ~

I have read and understood this condition guide.

Name:			

10 Apr 2019

~

Reversing camera

Date: