



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	17,959,782
Version:	3
Created:	16 Jul 2019

Make:	Subaru	Body Style:	SUV
Model:	Forester	VIN:	7AT0GF17X19014061
Year:	2008	Odometer:	97,439 Kms
Road Conditions During Test Drive:	Dry		

Electrical			30	Fuel Flap Release	<input checked="" type="checkbox"/>	Cooling System			78	Under Carriage	Good	Exterior		
1	Battery	<input checked="" type="checkbox"/>	31	Reversing Camera	<input checked="" type="checkbox"/>	55	Coolant Condition	<input checked="" type="checkbox"/>	79	Sun Roof Operation	<input type="checkbox"/>			
2	Headlights	<input checked="" type="checkbox"/>	32	USB Port	<input type="checkbox"/>	56	Performance	<input checked="" type="checkbox"/>	80	Front Windscreen (no chips)	Good			
3	Tail Lights	<input checked="" type="checkbox"/>	33	Window Lock Switch	<input type="checkbox"/>	57	Radiator/Hoses (visual)	<input checked="" type="checkbox"/>	81	Back Windscreen (no chips)	Good			
4	High Stop Light	<input type="checkbox"/>	Transmission and Drive			Suspension			82	Side Windows (no chips)	Good			
5	Front Right Indicators	<input checked="" type="checkbox"/>	34	Operation	<input checked="" type="checkbox"/>	58	Suspension Performance	<input checked="" type="checkbox"/>	83	Front Wiper Blades	Good			
6	Front Left Indicators	<input checked="" type="checkbox"/>	35	Noise	<input checked="" type="checkbox"/>	59	Steering Performance	<input checked="" type="checkbox"/>	84	Rear Wiper Blade	Good			
7	Rear Right Indicators	<input checked="" type="checkbox"/>	36	Clutch	<input type="checkbox"/>	60	Shock Absorbers	<input checked="" type="checkbox"/>	85	R/H Mirror	Good			
8	Rear Left Indicators	<input checked="" type="checkbox"/>	37	CV Joints	<input checked="" type="checkbox"/>	Wheels and Tyres			86	L/H Mirror	Good			
9	Reversing Lights	<input type="checkbox"/>	38	Wheel Bearing	<input checked="" type="checkbox"/>	61	Left Front	3.0 mm	87	L/F Guard	Good			
10	Rear Reflectors	<input type="checkbox"/>	39	Wheel Balance	<input checked="" type="checkbox"/>	62	Right Front	3.0 mm	88	R/F Guard	Good			
11	Hazard Lights	<input type="checkbox"/>	40	Gearbox (Manual)	<input type="checkbox"/>	63	Left Rear	6.0 mm	89	L/H Doors	Good			
12	Courtesy Lights	<input type="checkbox"/>	41	Engine Timing	Cambelt	64	Right Rear	6.0 mm	90	R/H Doors	Good			
13	Dashboard Lights	<input type="checkbox"/>	42	Evidence of Cam Belt Replacement	Yes	65	Spare	Yes	91	L/H Sill	Good			
14	Dashboard Dimmer Switch	<input type="checkbox"/>	43	Replaced at (odometer reading)	180,000	66	Tools	<input checked="" type="checkbox"/>	92	R/H Sill	Good			
15	Number Plate Light	<input type="checkbox"/>	Brakes			Interior			93	Boot/Tail Gate	Good			
16	Dashboard Warning Lights	<input checked="" type="checkbox"/>	44	Front Brakes	<input checked="" type="checkbox"/>	67	AC Operation	<input checked="" type="checkbox"/>	94	Front Bumper	Good			
17	Speedo	<input type="checkbox"/>	45	Rear Brakes	<input checked="" type="checkbox"/>	68	Heater Fan	<input checked="" type="checkbox"/>	95	Rear Bumper	Good			
18	Odometer	<input type="checkbox"/>	46	Handbrake	<input checked="" type="checkbox"/>	69	Seatbelts	<input checked="" type="checkbox"/>	96	Roof	Good			
19	Rev Counter	<input type="checkbox"/>	Keys and Locking			70	Horn	<input checked="" type="checkbox"/>	97	Bonnet	Good			
20	Fuel Gauge	<input type="checkbox"/>	47	Central Locking	<input checked="" type="checkbox"/>	71	Seat Heaters	<input type="checkbox"/>	98	Fuel Cap	<input checked="" type="checkbox"/>			
21	Wipers Front/Rear	<input checked="" type="checkbox"/>	48	Remote Locking	<input checked="" type="checkbox"/>	72	Sun Visors	<input checked="" type="checkbox"/>	99	Mud Flaps	<input checked="" type="checkbox"/>			
22	Window Opener FL	<input checked="" type="checkbox"/>	49	Number of Keys	1	73	Sun Visors Lights/Mirrors	<input checked="" type="checkbox"/>	100	WOF	<input checked="" type="checkbox"/>			
23	Window Opener FR	<input checked="" type="checkbox"/>	Engine			74	Seats	Good						
24	Window Opener RL	<input checked="" type="checkbox"/>	50	Oil Level	<input checked="" type="checkbox"/>	75	Carpets	Good						
25	Window Opener RR	<input checked="" type="checkbox"/>	51	Smokes and Fumes	<input checked="" type="checkbox"/>	76	Panels	Good						
26	Rear View Mirrors	<input checked="" type="checkbox"/>	52	Performance	<input checked="" type="checkbox"/>	77	Dashboard	Good						
27	Radio (Basic Test Only)	<input checked="" type="checkbox"/>	53	Noise	<input checked="" type="checkbox"/>									
28	CD (Basic Test Only)	<input checked="" type="checkbox"/>	54	Starter Motor	<input checked="" type="checkbox"/>									
29	Boot Open Switch	<input checked="" type="checkbox"/>												

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle