

Turners Certified Imports 50 Point Check

Report ID: 17,960,256

Version:

Created: 12 Apr 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Body Style: Sedan Nissan Make: Tiida Odometer: 15,702 Kms Model: 2012 7AT0DH78X19312720 VIN: Year:

Under Carriage & Under Bonnet Inspection Comments

Tidy.

General Comments

Tidy, low km Tiida sedan.

Seats: Good Carpets: Good Panels: Good Dashboard: Good		
Panels: Good	Seats:	Good
raneis.	Carpets:	Good
Dashboard: Good	Panels:	Good
	Dashboard:	Good

Timing Chain **Engine Timing Mechanism:** Not Applicable


Evidence of Cam Belt Replacement:


Replaced At (odometer reading):

Road Conditions During Test Drive:


Dry

Electrical			
Battery			
Head lights			
Tail lights			
Indicators			
Dashboard warning lights			
Wipers (front & rear)			
Window winder FL			
Window winder FR			
Window winder RL			
Window winder RR			
Rear view mirrors			
Radio (basic test only)			
CD (basic test only)	•		
Reversing camera	•		





Inspected by: Daryll Timms



Date: 12 Apr 2019