

Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	17,960,287
Version:	2
Created:	18 Sep 2019

Make:	Subaru	Body Style:	Hatchback
Model:	Impreza	VIN:	7AT0GF09X19046362
Year:	2011	Odometer:	79,098 Kms
Road Conditions During Test Drive:	Dry		

Ele	ctrical	30	Fuel Flap Release	Coo	oling System		Ext	erior	
1	Battery	31	Reversing Camera	55	Coolant Condition	n 🖌	78	Under Carriage	Good
2	Headlights	32	USB Port	56	Performance		79	Sun Roof Operation	•
3	Tail Lights	33	Window Lock Switch	57	Radiator/Hoses (v	isual)	80	Front Windscreen (no chips)	Good
4	High Stop Light	Tra	nsmission and Drive	Sus	pension		81	Back Windscreen (no chips)	Good
5	Front Right Indicators	34	Operation	58	Suspension Perfo	rmance	82	Side Windows (no chips)	Good
6	Front Left Indicators	35	Noise	59	Steering Perform	ance	83	Front Wiper Blades	Good
7	Rear Right Indicators	36	Clutch	60	Shock Absorbers		84	Rear Wiper Blade	Good
8	Rear Left Indicators	37	CV Joints	Wh	eels and Tyres		85	R/H Mirror	Good
9	Reversing Lights	38	Wheel Bearing	61	Left Front	5 mm	86	L/H Mirror	Good
10	Rear Reflectors	39	Wheel Balance	62	Right Front	6 mm	87	L/F Guard	Good
11	Hazard Lights	40	Gearbox (Manual)	63	Left Rear	6 mm	88	R/F Guard	Good
12	Courtesy Lights	41	Engine Timing Cambelt	64	Right Rear	6 mm	89	L/H Doors	Good
13	Dashboard Lights	42	Evidence of Cam Belt Replacement	65	Spare	Yes	90	R/H Doors	Good
14	Dashboard Dimmer Switch	43	Replaced at (odometer reading)	66	Tools		91	L/H Sill	Good
15	Number Plate Light	Bra	kes	Inte	Interior		92	R/H Sill	Good
16	Dashboard Warning Lights	44	Front Brakes	67	AC Operation		93	Boot/Tail Gate	Good
17	Speedo	45	Rear Brakes	68	Heater Fan		94	Front Bumper	Good
18	Odometer	46	Handbrake	69	Seatbelts		95	Rear Bumper	Good
19	Rev Counter	Key	vs and Locking	70	Horn		96	Roof	Good
20	Fuel Gauge	47	Central Locking	71	Seat Heaters		97	Bonnet	Good
21	Wipers Front/Rear	48	Remote Locking	72	Sun Visors		98	Fuel Cap	
22	Window Opener FL	49	Number of Keys 2	73	Sun Visors Lights/Mirrors		99	Mud Flaps	
23	Window Opener FR	Eng	gine	74	Seats	Good	100	WOF	
24	Window Opener RL	50	Oil Level	75	Carpets	Good			
25	Window Opener RR	51	Smokes and Fumes	76	Panels	Good			
26	Rear View Mirrors	52	Performance	77	Dashboard	Good			
27	Radio (Basic Test Only)	53	Noise				Turn	ers Certification K	ey:
28	CD (Basic Test Only)	54	Starter Motor				$\checkmark = F$ ×= F		
29	Boot Open Switch							lot applicable for thi	s vehicle

Inspected by:	Daryll Timms	Date:	18 Sep 2019				
I have read and understood this condition guide:							
Name:		Signature:					