

## **Basic Vehicle Condition Guide**

Report ID: 17,960,959

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

**Transmission** 

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Right front

Left rear

Right rear

Suspension

Suspension performance Steering performance

Shock absorbers Air Conditioning / Heater

**Electrical / Accessories** 

Dashboard warning lights

Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Operation

Head lights Tail lights Indicators

Spare

Coolant condition Performance

Radiator / Hoses (visual)

Created: 07 Nov 2018

Fail

Pass

1

/

/

1

Tyres (lowest observed tread depth of tyres)

N/A

1

mm

mm

mm

 $\mathsf{mm}$ 

3

3

3

1

/

1

1

1


1

Yes

Make: Model: **Body Style:** Sedan Skoda Octavia Year: Registration: Reg Expiry: 2011 FYA625 12 Aug 2019 WoF Expiry: **Odometer:** 20 Jul 2019 **Good No:** 17960959 165,761 Kms VIN: TMBCT61Z0B2132607 **Next Service: Service History:** Flexi No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

Note: some defects & blemishes may not be displayed in the diagram

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Interior Comments				
Seats	Average			
Carpets	Average			
Panels	Average			
Dashboard	Average			

	_
Conoral	Comments
General	Comments

Road Conditions During Test Drive: Dry	Central locking	V		
-	Remote locking	V		
Engine Timing Mechanism: Cambelt		Sat. Nav. (basic test only)		~
Evidence of Cam Belt Replacement: No	Kms:	Reversing camera		~
Inspected by: Donovan Matara	Date: 07 Nov 2018			
nave read and understood this condition guide.	Name: Signature:			