

Report ID: 17,961,511 Version: 2 26 Nov 2018 Created:

Signature: .....

Make:	Mitsubishi	Model:	Triton	Body Style:	Utility	٦٢		Pass	Fail	N/A	
Year:	2012	<b>Registration:</b>	GGH447	<b>Reg Expiry:</b>	28 Feb 2019		Engine	•	•	•	
WoF Expiry:	19 Nov 2019	Odometer:	156,024 Kms	Good No:	17961511		Oil level	~			
VIN:	MMAJNKA40CD00235	Next Service:	166000	Service Histor	<b>y:</b> No		Smoke & fumes	~			
						٦ŀ	Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or							Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Cooling System			•	
							Coolant condition	~			
			S D			٦Ľ	Performance	~			
Key:		-0		-01-			Radiator / Hoses (visual)	~			
S = scratch						١ħ	Fransmission			1	
D = dent R = rust SSC							Operation	~			
PT = paint defe	ect NP	r I		$\left[ \left( \right) \right]$			Noise	~			
C = crack					S SC		Clutch	~			
P = pin dent	HID			$\langle \rangle$	7414		CV joints	~			
* = decals	- All			Ta	FID SD		Wheel bearings	~			
SC = stone chips							Brakes				
W = significant scuffs							Performance	~			
Bodylac		Note: son	ne defects & blemishes	s may not be disp	layed in the diagram		Hand Brake	~			
Body Inspection Comments							<b>Tyres</b> (lowest observed tread depth of tyres)				
							Left front		5	mm	
							Right front		5	mm	
						╧	Left rear		5	mm	
Conditions During Body Inspection: Wet						٦ŀ	Right rear		5	mm	
						┙┟	Spare Yes				
Under Carriage & Under Bonnet Inspection Comments							Suspension				
						IF	Suspension performance	~			
							Steering performance	· ·			
							Shock absorbers	~			
							Air Conditioning / Heater		I	I	
							Operation	~			
Interior Comments							Electrical / Accessories	-		1	
Seats	minor stai	ns ,					Head lights	~			
	A						Tail lights	• •			
Carpets	Average						Indicators	• •		-	
Panels	Average						Dashboard warning lights	· ·			
							Wipers (front & rear)	• •			
Dashboa	ard Average						Window winder FL	• •			
						┙┟	Window winder FR	• •			
General C	<u>Comments</u>					11	Window winder RL	• •			
							Window winder RR	~			
							Rear view mirrors	~			
							Radio (basic test only)	~			
							CD (basic test only)	~			
						┨┠	Number of keys	3			
						╕┠	Central locking	 ✓			
Road Conditions During Test Drive: Wet						┛┠	Remote locking	v v			
Engine Timing Mechanism: Cambelt						╕┠	Sat. Nav. (basic test only)	•			
Evidence of Cam Belt Replacement: No Kms:								~		~	
							Reversing camera	~			
Inspected by: Donovan Matara Date: 26 Nov 2018											

I have read and understood this condition guide.

Name: .....