

Report ID: 17,962,489 Version: 1 09 Jan 2019 Created:

Make:	Nissan	Model:	Navara	Body Style:	Utility		Pass	Fail	N/A
Year:	2013	Registration:	LUA138	Reg Expiry:	16 Jan 2019	Engine	1		
WoF Expiry:	19 Dec 2019	Odometer:	131,676 Kms	Good No:	17962489	Oil level	~		
VIN:	VSKCVAD40A0506456	Next Service:	141357	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
diagnostic tes	sting undertaken. The	vehicle has beer	n driven up to 50km/h	from cold. The	Vendor recommends	Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
	SC		S SC S SC		S SC	Performance	~		
Key:		-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent	AL				Tan	Transmission			1
D = defit R = rust				710	HIV	Operation	~		
PT = paint defe	ect NP				10111	Noise	~		
C = crack						Clutch			~
P = pin dent	ssc dR				7411L	CV joints	~		
* = decals				Tool .		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w = significant	SC				S	Performance	~		
Body Incr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
						Left front	7	7	mm
						Right front	7	7	mm
						Left rear	e	5	mm
Conditions During Body Inspection: Dry						Right rear	6 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	drivers sea	it ripped,wear an	id tear ,			Head lights	~		
	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry Central							~		
			•			Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Donovan Matara Date: 09 Jan 2019									

I have read and understood this condition guide.

Name:

Signature: