

Basic Vehicle Condition Guide

Report ID: 17,962,518


Version: 1

11 Dec 2018

Make: Model: **Body Style:** Mazda Bt-50 Utility Year: 2010 Registration: FPU45 Reg Expiry: 29 Sep 2019 WoF Expiry: **Odometer: Good No:** 05 Dec 2019 206,387 Kms 17962518 VIN: MM0UNY0E40087510 **Next Service:** 216300 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Average		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:**

No

Kms:

Donovan Matara Inspected by:

Create	u. 1		.010
	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\triangle \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	\(\times \)		
Clutch	~		
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	9		mm
Right front	9		mm
Left rear	9		mm
Right rear	9		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater	<u> </u>		1
Operation	~		
Electrical / Accessories			1
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	\(\times \)		
Window winder FL	<i>v</i>		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
	~		
Radio (basic test only)			
CD (basic test only)	2		
Number of keys	2		
Central locking	'		
Remote locking			_
Sat. Nav. (basic test only)			V
Reversing camera	l	1	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \

I have read and understood this condition guide.

Name:

Signature:

11 Dec 2018

Date: