

Report ID: 17,963,761 Version: 1 24 Jan 2019 Created:

Make:	Subaru	Model:	Legacy	Body Style:	Wagon	] [	Pass	Fail	N/A
Year:	2008	Registration:		<b>Reg Expiry:</b>	25 Jan 2019	Engine			L
WoF Expiry:	13 Dec 2019	Odometer:	146,992 Kms	Good No:	17963761	Oil level	~		
VIN:	7AT0GF0BX13161215	Next Service:	156,900	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SP S	-0	s sc s sc		W	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust				715	S PT SC	Operation	~		
PT = paint defe				$\left( \left  \right\rangle \right)$		Noise	~		
C = crack					S SC	Clutch			~
P = pin dent	110				세비	CV joints	~		
* = decals	SPSC 916			- No	ELD SW	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S P SC S S C W S P SC W S P SC W S P SC W						Performance	~		
Dealerteen		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			es)
Left front bumper needs alignment,						Left front			
						Right front	3		mm
						Left rear			mm
Conditions During Body Inspection: Dry						Right rear		2 mn	
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Window wa	asher fluid cap missing,c	oil leak.				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	minor stair	ns				Head lights	~		
50005						Tail lights	~		
Carpets	Good					Indicators	~		$\left  - \right $
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd scratches					Window winder FL	~		
						Window winder FR	~		
<u>General</u> C	<u>Comments</u>					Window winder RL	~		
Rattles when idling.						Window winder RR	~		<u> </u>
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	· ·		
Koad Con	attions During Test	u Drive:	Dry			Remote locking	~		
Engine Ti	ming Mechanism:	Cambelt	t			Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Yes Kms: 138,000						Reversing camera			<i>v</i> <i>v</i>
					_,				
Inspected by: Donovan Matara Date: 24 Jan 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....