

Report ID: 17,963,902 Version: 1 05 Feb 2019 Created:

Make:	BMW	Model:	3 Series	Body Style:	Sedan		Pass	Fail	N/A
Year:	2008	Registration:	HNW60	Reg Expiry:	23 May 2019	Engine		·	
WoF Expiry:	14 Jan 2020	Odometer:	135,844 Kms	Good No:	17963902	Oil level	~		
VIN:	WBAVH36060NL0725	Next Service:	145800	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		1
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0		-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	- HE			715	SW	Operation	~		1
R = rust PT = paint defe				$\left(\left \right\rangle \right)$		Noise	~		
C = crack				$+ \nabla$		Clutch	-		~
P = pin dent					세비	CV joints	~		<u>├</u>
* = decals	ssc 916			-NL	ELIPS S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S D SC W S D SC W S D SC W						Performance	~		
		Note: son	ne defects & blemishe	s may not be disr	blaved in the diagram	Hand Brake	~		-
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•	oftvre	
Minor stone chips in the windscreen ,						Tyres (lowest observed tread depth of tyres) Left front 5 mm			
						Right front			mm
						Left rear		5	-
			_					5	mm
Conditions During Body Inspection: Dry						Right rear	5 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage a onder bor	meenspeede	<u>eennents</u>			Suspension			1
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			T
Interior Comments						Operation 🖌			
Average						Electrical / Accessories			
Seats	riveruge					Head lights	~		
Carpets	slight rip o	on drivers floor ,				Tail lights	~		
	drivers do	or trim ripped ar	nd LF door handle,			Indicators	~		
Panels		or unit tipped af				Dashboard warning lights	~		<u> </u>
Dashboa	Average					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		<u> </u>
Campada						Window winder FR	~		<u> </u>
General	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
	-		•			Remote locking	~		
-	ming Mechanism:	Unknow	/n			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected	d by: Donovan Matar	a				Date: 05 Feb 20	19		

I have read and understood this condition guide.

Name:

Signature: