

Basic Vehicle Condition Guide

Report ID: 17,963,925


Version: 1

Created: 10 Dec 2018

Make: Model: H1 Hyundai **Body Style:** Van Year: 2010 Registration: FKP26 Reg Expiry: 29 Sep 2019 WoF Expiry: **Odometer:** 30 Aug 2019 151,262 Kms **Good No:** 17963925 VIN: KMFWBX7JLAU25934 Next Service: 158000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Minor stone chips in the windscreen,

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | | | | |
|-------------------|--|--|--|--|
| Seats | drivers seat ripped,minor stains,wear and tear , | | | |
| Carpets | wear and tear , | | | |
| Panels | Average | | | |
| Dashboard | Average | | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Donovan Matara Date:

Name:

| | Cleate | u. 10 |) DCC 2 | .010 | | |
|--------|--|--------------|---------|----------|--|--|
| | | Pass | Fail | N/A | | |
| | Engine | | | | | |
| | Oil level | ~ | | | | |
| | Smoke & fumes | V V | | | | |
| 1 | Performance | ~ | | | | |
| | Noise | ~ | | | | |
| | Cooling System | • | | | | |
| | Coolant condition | ~ | | | | |
| | Performance | <i>v</i> | | | | |
| | Radiator / Hoses (visual) | ~ | | | | |
| | Transmission | | | | | |
| | Operation | ~ | | | | |
| | Noise | ~ | | | | |
| | Clutch | <i>V V</i> | | | | |
| | CV joints | ~ | | | | |
| | Wheel bearings | ~ | | | | |
| | Brakes | | | | | |
| | Performance | ~ | | | | |
| | Hand Brake | ~ | | | | |
| | Tyres (lowest observed tread depth of tyres) | | | | | |
| | Left front | 7 | 7 | | | |
| | Right front | 7 | | mm | | |
| | Left rear | 7 | | mm | | |
| | Right rear | 7 | | mm | | |
|]] | Spare | Yes | | | | |
| | Suspension | | | | | |
| | Suspension performance | ~ | | | | |
| | Steering performance | ~ | | | | |
| | Shock absorbers | > | | | | |
| | Air Conditioning / Heater | | | | | |
| 1 | Operation | > | | | | |
| | Electrical / Accessories | | | | | |
| | Head lights | ~ | | | | |
| | Tail lights | ~ | | | | |
| | Indicators | ~ | | | | |
| | Dashboard warning lights | \(\times \) | | | | |
| | Wipers (front & rear) | ~ | | | | |
| | Window winder FL | ~ | | | | |
| , 1 | Window winder FR | ~ | | | | |
| | Window winder RL | | | ~ | | |
| | Window winder RR | | | ~ | | |
| | Rear view mirrors | ~ | | | | |
| | Radio (basic test only) | ~ | | | | |
| | CD (basic test only) | ~ | | | | |
| | Number of keys | 2 | | | | |
| | Central locking | ~ | | | | |
| 1 1 | Remote locking | ~ | | | | |
| | Sat. Nav. (basic test only) | | | ~ | | |
| | Reversing camera | | | ' | | |
| | | | | | | |

10 Dec 2018

Signature: