

Report ID: 17,964,125 Version: 1 11 Dec 2018 Created:

Make:	Holden	Model:	Colorado	Body Style:	Utility][Pass	Fail	N/A	
Year:	2009	Registration:	EZN113	Reg Expiry:	25 Sep 2019	Engine				
WoF Expiry:	07 Jun 2019	Odometer:	237,507 Kms	Good No:	17964125	Oil level	~			
VIN:	MMMTFR85H8H57356	Next Service:	0	Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	lical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	~			
						Performance	~			
Key:	S SC	-0	S D SC	-01-	S D SC	Radiator / Hoses (visual)	~			
S = scratch						Transmission	Transmission			
D = dent R = rust	s sc			715	HILL	Operation	~			
PT = paint defe		FI		$\left[\left(\right) \right]$		Noise	~			
C = crack				+	S D SC	Clutch	~			
P = pin dent	HID				7414	CV joints	~			
* = decals	s sc 916			- Jul	SDC SC	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs S D SC S D S D S D C SC						Performance	~			
Dealerteen		Note: son	ne defects & blemishe	s may not be disp	blayed in the diagram	Hand Brake	~			
body inspection comments						Tyres (lowest observed tread depth of tyres			L es)	
Minor stone chips in the windscreen ,RF door mirror glass has lines on it,						Left front 6 mm				
						Right front		5	mm	
						Left rear		5	mm	
Conditions Duving Pody/Inspection, Dry						Right rear		5	mm	
Conditions During Body Inspection: Dry						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
	-	•				Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~		+	
						Air Conditioning / Heater	v			
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats wear and tear,stained ,						Head lights	~			
Jeats						Tail lights	~			
Carpets	Average					Indicators	~		+	
Danala	Average					Dashboard warning lights	~			
Panels						Wipers (front & rear)	<i>v</i> <i>v</i>			
Dashboa	rd screw hole	es in dash ,				Window winder FL	~		+	
						Window winder FR	<i>v</i> <i>v</i>			
General C	Comments					Window winder RL	-		~	
						Window winder RR			<i>v</i> <i>v</i>	
						Rear view mirrors	~			
						Radio (basic test only)	<i>v</i> <i>v</i>			
						CD (basic test only)	<i>v</i> <i>v</i>			
						Number of keys				
						, <u> </u>	3		1	
Koad Con	ditions During Test	t Drive:	Dry			Central locking	V 			
Enaine Tir	ming Mechanism:	Timing	Chain			Remote locking	~			
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~	
						Reversing camera			~	
Inspecte	d by: Donovan Matar	a				Date: 11 Dec 20	18			
	-									

I have read and understood this condition guide.

Name:

Signature: