

I have read and understood this condition guide.

Signature:

Make:	Mitsubishi	Model:	Lancer	Body Style:	Sedan		Pass	Fail	N/A
Year:	2006	Registration:	DPH89	Reg Expiry:	22 Jan 2019	Engine		1	•
WoF Expiry:	18 Jul 2018	Odometer:	276,606 Kms	Good No:	17964398	Oil level	~		
VIN:	JMFSNCS7A6U004824	Next Service:	0	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
	S SC		S PT P SC S PT P S		S PT P SC	Performance	~		
Key: S SC S PT P SC S PT P SC S = scratch D = dent S D C SC S D C SC R = rust S D C SC S PT SC S PT SC PT = paint defect C = crack S PT SC						Radiator / Hoses (visual)	~		
						Transmission			
						Operation	~		
						Noise	r		
						Clutch	r		
P = pin dent						CV joints	~		
* = decais						Wheel bearings	V		
SC = stone chips						Brakes			
W = significant scuffs S SC S D SC S D SC S D SC						Performance	~		
Body Incr	oction Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Clear coat coming off the roof ,boot lid different colour ,						Tyres (lowest observed tread depth of tyres)			es)
Clear coat coming on the rooi ,boot lid different colour ,						Left front 7 mi			
						Right front		7	mm
						Left rear		5	mm
Conditions During Body Inspection: Dry						Right rear		5	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Minor oil leak ,						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	I		
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	wear and tear,cigarette holes,minor stains ,					Head lights	~		
	Average					Tail lights	V		
Carpets	Avelage					Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
-						Window winder FR	~		
General Comments						Window winder RL	~		
Ignition doesn't open boot lid ,						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
Inspected by: Donovan Matara Date: 11 Dec 2018									

Name: