

Basic Vehicle Condition Guide

Report ID: 17,970,695

Version: 1


Created: 21 Nov 2018

Pass Fail N/A

Make: Model: Mitsubishi Triton **Body Style:** Utility Year: 2013 Registration: HFB625 Reg Expiry: 29 Mar 2019 WoF Expiry: **Odometer:** 05 Dec 2019 64,221 Kms **Good No:** 17970695 VIN: MMAJNKA40DD00995 Next Service: 77000 **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Right cant rail small dent,

Conditions	Durina	Bodv	Inspection:	Drv

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>		
Seats	Good	
Carpets	Good	
Panels	Good	
Dashboard	Good	

General	Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Chris Buckley

Kms:

~		
~		
~		
~		
	•	•
~		
~		
~		
	!	
~		
~		
~		
~		
~		
~		
~		
depth	of tyre	es)
8	.0	mm
8.0		mm
8.0		mm
8.0		mm
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
·		
·		
2		
·		
		
~		
	8 8 8 7 7 7 7 7 7 7 7 7 7 7 7 7	マ

I have read and	understood	this conditio	n guide.

20 Nov 2018

~

Reversing camera