

Report ID: 17,970,844 Version: 1 07 Dec 2018 Created:

Make:	Toyota	Model:	Altezza	Body Style:	Sedan	$\ $		Pass	Fail	N/A	
Year:	1999	Registration:	DDR937	Reg Expiry:	01 Feb 2019		Engine				
WoF Expiry:	19 Apr 2019	Odometer:	352,361 Kms	Good No:	17970844		Oil level	~			
VIN:	7A8H6390703018441	Next Service:	350000	Service Histor	r y: No][Smoke & fumes	~			
Notes This wa						۱Ì	Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or							Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Cooling System				
							Coolant condition	~			
	DW		PT			٦Ì	Performance	~			
Key: S = scratch						l	Radiator / Hoses (visual)	~			
							Transmission				
R = rust PT = paint defect							Operation	~			
							Noise	~			
C = crack							Clutch	~			
P = pin dent							CV joints	~			
							Wheel bearings	~			
SC = stone chips W = significant scuffs							Brakes				
							Performance	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							Hand Brake	~			
/							Tyres (lowest observed tread depth of tyres)				
							Left front	5	.0	mm	
						l	Right front	5.	.0	mm	
						IJ	Left rear	5	.0	mm	
Conditions During Body Inspection: Dry						ון	Right rear	5	.0	mm	
						ļ	Spare Yes				
Under Carriage & Under Bonnet Inspection Comments							Suspension				
/							Suspension performance	~			
							Steering performance	~			
							Shock absorbers	~			
							Air Conditioning / Heater				
							Operation 🖌				
Interior Comments							Electrical / Accessories				
Seats	R/F Seat V	Vorn					Head lights	~			
Corrota	Good						Tail lights	~			
Carpets							Indicators	~			
Panels	Good						Dashboard warning lights	~			
	Good						Wipers (front & rear)	~			
Dashboa	ira						Window winder FL	~			
	_					ij	Window winder FR	~			
General Comments							Window winder RL	~			
Service due , key Broken , L/H Mirror N/W, R/F Headlight low beam bulb out , R/F sun visor worn ,							Window winder RR	~			
							Rear view mirrors	~			
							Radio (basic test only)	~			
							CD (basic test only)	~			
						<u>ا ۲</u>	Number of keys	1			
Road Conditions During Test Drive: Dry							Central locking	~			
En aire a Tinaine Machanianu - Carabalu						;[Remote locking	~			
Engine Timing Mechanism: Cambelt							Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement:YesKms:307,000							Reversing camera			~	
Inspected by: Chris Buckley Date: 07 Dec 2018											
Inspected by, Chris Buckley Date: 07 Dec 2018											

I have read and understood this condition guide.

Name:

Signature: