

Report ID: 17,971,177 Version: 1 05 Feb 2019 Created:

| Make: | Holden | Model: | Colorado | Body Style: | Utility | | Pass | Fail | N/A |
|--|--------------------------|-----------------|------------------------|---------------------|---------------------|--|--------|--------|----------|
| Year: | 2016 | Registration: | KCF505 | Reg Expiry: | 26 Jan 2019 | Engine | | | |
| WoF Expiry: | 27 Sep 2019 | Odometer: | 61,753 Kms | Good No: | 17971177 | Oil level | ~ | | |
| VIN: | MMU148LK0HH60451 | Next Service: | 62000 | Service Histor | y: Yes | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | aration is made | for age and mileage | Parts have not | been dismantled or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and t | nis can be arranged fo | or an additional o | charge. | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | SDSC | -0 | S D | -01- | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| | | | | | | Operation 🖌 | | | |
| R = rust PT = paint defe | | | | \int | | Noise | ~ | | |
| C = crack | | | | $+ \mathbf{\nabla}$ | SC | Clutch | • | | ~ |
| P = pin dent | | | | | | CV joints | ~ | | • |
| * = decals | sc 916 | | | - NL | ETP D | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs SC D D SC | | | | | | Performance | ~ | | |
| | | Note: son | ne defects & blemishe | s may not be disr | | Hand Brake | ~ | | |
| 1 | pection Comments | 1016.301 | le délects & biemisne | s may not be disp | ayed in the diagram | | - | ofture | () () |
| Tailgate Wont open , | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | | Left front | | .0 | mm |
| | | | | | | Right front | 7. | | mm |
| | | | | | | Left rear | 8. | | mm |
| Conditions During Body Inspection: Wet | | | | | | Right rear | 8.0 mm | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Spare Yes | | | |
| | mage & onder bor | inet inspectic | on comments | | | Suspension | 1 | 1 | |
| / | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | I | |
| | | | | | | Operation 🖌 | | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| Caract | Good | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| | , Good | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | ra | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General C | <u>Comments</u> | | | | | Window winder RL | ~ | | |
| / | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | | | ~ |
| | | | | | | Number of keys | 2 | I | I |
| Road Conditions During Test Drive: Wet | | | | | | Central locking | ~ | | |
| | | | | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | ~ | | |
| Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Reversing camera | ~ | | |
| | • | | | | | | - | | |
| Inspected by: Chris Buckley Date: 07 Jan 2019 | | | | | | | | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: