

Report ID: 17,971,371 Version: 4 18 Feb 2019 Created:

Make:	Mitsubishi	Model:	Outlander	Body Style:	SUV		Pass	Fail	N/A	
Year:	2014	Registration:	HWG881	<b>Reg Expiry:</b>	28 Mar 2019	Engine	1			
WoF Expiry:	13 Feb 2020	Odometer:	178,859 Kms	Good No:	17971371	Oil level	~			
VIN:	JMFXTGF8WEZ006682	Next Service:	165000	Service Histor	<b>y:</b> Yes	Smoke & fumes	V			
						Performance	~			
	port is not a warranty a guide only. Conside	aration is made	for age and mileage	a Parts have not	been dismantled or	Noise	V			
diagnostic te	sting undertaken. The	vehicle has beer	n driven up to 50km/	h from cold. The	Vendor recommends	Cooling System				
a full mechan	ical inspection prior to	purchase and th	nis can be arranged f	or an additional o	harge.	Coolant condition	V			
						Performance	~			
Key:		-0	D P	-01-		Radiator / Hoses (visual)	~			
S = scratch						Transmission	-			
D = dent R = rust SC						Operation	~			
PT = paint defe				$\left[ \right] \left[ \right] \left[ \right]$		Noise	~			
C = crack				$+ \mathbb{N}$	P SC	Clutch			~	
P = pin dent	110				거네	CV joints	~		-	
* = decals	PSC 916			The	ELD D	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs W P P						Performance	~			
Dealer		Note: som	ne defects & blemishe	es may not be disc	blayed in the diagram	Hand Brake	~			
body inspection comments						Tyres (lowest observed tread	•	of tvre	s)	
Roof minor spider rust ,						Left front 6.0 mm				
						Right front	6		mm	
						Left rear	6		mm	
Conditions Duving Pody Inspection						Right rear		.0	mm	
Conditions During Body Inspection: Dry						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
	t on exhaust system ,	·				Suspension performance	~			
	<b>,</b> , , , , , , , , , , , , , , , , , ,					Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater	•			
						Operation		~		
Interior Comments						Electrical / Accessories		•		
Seats	Good					Head lights	~			
Jeats						Tail lights	~			
Carpets	Good						~			
Danala	Good					Dashboard warning lights	~			
Panels						Wipers (front & rear)	~			
Dashboa	rd Good					Window winder FL	~			
	I					Window winder FR	~			
General Comments					Window winder RL	~				
Service Due , , W/Screen Chip ,					Window winder RR	~				
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry						Central locking	2 V			
Koad Con	attions During Test	Urive:	Dry			Remote locking	~			
Engine Tir	ming Mechanism:	Timing (	Chain			Sat. Nav. (basic test only)	-		~	
-	of Cam Belt Replac	-	lot Applicable	Kms:		Reversing camera	~			
	-1		- Flammana				•			
Inspected	Inspected by: Chris Buckley Date: 24 Jan 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....