

Basic Vehicle Condition Guide

Report ID: 17,971,760


Version: 1

Created: 14 Feb 2019

Make: Model: **Body Style:** Hyundai Santa FE SUV Year: 2015 Registration: HYA726 Reg Expiry: 25 Apr 2019 WoF Expiry: **Odometer: Good No:** 15 Jan 2020 181,144 Kms 17971760 VIN: KMHST81XSFU438067 **Next Service:** 187000 Service History: No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Rear Bumper Valance Cracked,

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

(1eneral	Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Chris Buckley

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	<i>y y y y</i>		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	>		
Radiator / Hoses (visual)	~		
Transmission			
Operation	'		
Noise	>		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	'		
Tyres (lowest observed tread	l depth	of tyre	es)
Left front	7	.0	mm
Right front	7.0		mm
Left rear	4	.0	mm
Right rear	4	.0	mm
Spare		Yes	
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	/		
Tail lights	~		
Indicators	~		
Dashboard warning lights	\(\times \) \(\t		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	'		
Window winder RL	~		
Window winder RR	V		
Rear view mirrors			
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			'

I have read and understood this condition guide.

Name:

Signature:

14 Feb 2019

Date: