

Report ID: 17,973,181 Version: 3 Created: 04 Jul 2019

| Make: | Ford | Model: | Ranger | Body Style: | Utility | | Pass | Fail | N/A |
|---|---------------------|----------------------|----------------|--------------------|---------------|------------------------------|----------------------|---------|----------|
| Year: | 2014 | Registration: | | Reg Expiry: | 22 Jul 2019 | Engine | | | |
| WoF Expiry: | 17 Jul 2020 | Odometer: | 131,001 Kms | Good No: | 17973181 | Oil level | ~ | | |
| VIN: | MNAUMFF50EW2913 | Next Service: | 141000 | Service Histor | y: Yes | Smoke & fumes | r | | |
| | | | | | | Performance | ~ | | |
| Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or | | | | | | Noise | ~ | | |
| diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| | | | | | | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | | -0 | | -01- | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent R = rust SC A A A A A A A A A A A A A A A A A A | | | | | | Operation | ~ | | |
| PT = paint defect | | | | | | Noise | ~ | | |
| C = crack | | | | | | Clutch | ~ | | |
| P = pin dent | | | | | | CV joints | ~ | | |
| * = decals SC Q Q | | | | | | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs | | | | | | Performance 🖌 | | | |
| Redulars a some defects & blemishes may not be displayed in the diagram | | | | | | Hand Brake | ~ | | |
| body inspection comments | | | | | | Tyres (lowest observed tread | • | of tyre | l es) |
| RT Holes in centre console, | | | | | | Left front 12 | | | mm |
| | | | | | | Right front | | | mm |
| | | | | | | Left rear | | 5 | mm |
| Conditions During Body Inspection: Day | | | | | | Right rear | | 5 | mm |
| Conditions During Body Inspection: Dry | | | | | | Spare | Yes | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| / | - | | | | | Suspension performance | ~ | | 1 |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | • | | |
| | | Operation | ~ | | 1 | | | | |
| Interior Comments | | | | | | Electrical / Accessories | • | | |
| Seats | Good | | | | | Head lights | ~ | | |
| | | | | | | Tail lights | ~ | | |
| Carpets | Good | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| Pariels | | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd Good | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General (| <u>Comments</u> | | | | | Window winder RL | ~ | | |
| Service Due, Exhaust leak from front , | | | | | | Window winder RE | <i>v</i> <i>v</i> | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | | | |
| | | | | | | CD (basic test only) | ~ ~ | | |
| | | | | | | Number of keys | 2 | | <u> </u> |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | 2 | | T |
| Koad Con | aitions During Test | Drive: | Dry | | | Remote locking | <i>v</i> <i>v</i> | | |
| Engine Timing Mechanism: Timing Chain | | | | | | | | | |
| - | of Cam Belt Replac | - | lot Applicable | Kms: | | Sat. Nav. (basic test only) | | | ~ |
| | | | | | | Reversing camera | ~ | | |
| Inspected by: Donovan Matara | | | | | | Date: 04 Jul 2019 | | | |
| | | | | | | | | | |
| I have read and understood this condition guide. Name: | | | | | | | | | |