

Report ID: 17,973,467 Version: 1 10 Jun 2019 Created:

	Honda	Model:	Odyssey	Body Style:	Wagon		Pass	Fail	N/A
Year:	2000	Registration:	DLS234	Reg Expiry:	21 Aug 2019	Engine			
WoF Expiry:		Odometer:	310,596 Kms	Good No:	17973467	Oil level		~	T
	7A88G610706095063		510,57015	Service Histor		Smoke & fumes	~	•	<u> </u>
						Performance	~		
	oort is not a warranty		~ · · ·			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~	•	
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch	STE	A CO	$\overline{\frown}$	100	X	Transmission	•		
D = dent	SD 6/6				ED SD	Operation	~		Τ
R = rust					JHIH	Noise	~		-
PT = paint defe C = crack			-	+	D SC	Clutch			~
P = pin dent	Ho				JUII —	CV joints	~		
* = decals	sc pp				ETTR-	Wheel bearings			+
SC = stone chips							~		
W = significant scuffs D W S D D						Brakes Performance			T
		Noto: com					V		─
	ection Comments		ie delects & plemisn	es may not be disp	played in the diagram	Hand Brake		of to a	
Glove Box Br	roken , L/R Taillight Cra	cked,				Tyres (lowest observed tread		,	
						Left front	-	.0	mm
						Right front		.0	mm
						Left rear		.0	mm
Conditions During Body Inspection: Dry					Right rear	7.0 mm			
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	-	•				Suspension			T
OII leak lowe	er engine area, surface	rust on under of	venicie.			Suspension performance	~		<u> </u>
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater	1	1	
Interior Co	omments					Operation	~		
	Average					Electrical / Accessories		1	
Seats	Average					Head lights	~		<u> </u>
Carpets	Average					Tail lights	~		
	A					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboar	Average					Wipers (front & rear)	~		
Dastibuar	u -					Window winder FL	~		
	_					Window winder FR	~		
<u>General Comments</u> ABS light on Dash Display, Noise in Front Drive line ,					Window winder RL	~			
ABS light on	Dash Display, Noise in	Front Drive line	,			Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
	Road Conditions During Test Drive: Dry							~	
 Road Conc	ditions During Test	. Drive:							1.
						Remote locking			~
Engine Tin	ning Mechanism:	Cambel				Remote locking Sat. Nav. (basic test only)			~ ~
Engine Tin		Cambel		Kms:					
Engine Tin Evidence c	ning Mechanism:	Cambel	t	Kms:		Sat. Nav. (basic test only)			~