

Report ID: 17,973,479 Version: 3 09 Aug 2019 Created:

Make:	Holden	Model:	Colorado	Body Style:	Utility		Pass	Fail	N/A
Year:	2015	Registration:		Reg Expiry:	25 Dec 2019	Engine			L
WoF Expiry:		Odometer:	170,760 Kms	Good No:	17973479	Oil level	~		
VIN:	MMU145DK0FH62349	Next Service:		Service Histor	y: Yes	Smoke & fumes	~		<u> </u>
	·					Performance	~		<u> </u>
	port is not a warranty	aration is made	for ago and milaago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SD	-0	SD SD	-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission	Transmission		
D = dent R = rust	SC DE			715	HIL	Operation	~		
PT = paint defe		F I		$\left(\left \left(\right) \right\rangle \right)$		Noise	~		
C = crack					S P SC	Clutch	~		
P = pin dent	SDSC DR				74116	CV joints	~		
* = decals				Tool .		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w = significan			S D			Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
						Left front	5.0 mm		mm
						Right front	6.	.0	mm
						Left rear	5.	.0	mm
Conditions During Body Inspection: Wet Right rear						Right rear	6.	.0	mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
Shock absorbers							~		
Air Conditioning / Hea									
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Comoto	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dealth	Average					Wipers (front & rear)	~		
Dashboa	ru					Window winder FL	~		
	-					Window winder FR	~		
General Comments						Window winder RL			~
						Window winder RR			~
						Rear view mirrors	<		
						Radio (basic test only)	1		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Wet Central locking									
		Carala II				Remote locking	~		
Engine Timing Mechanism: Cambelt Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: Y	es	Kms: 17	70,796	Reversing camera			~
Inspected by: Chris Buckley Date: 11 Jun 2019									
Inspected by. Chris buckley Date: 11 Jun 2019									

I have read and understood this condition guide.

Name:

Signature: