

# **Basic Vehicle Condition Guide**

Report ID: 17,973,716

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

**Transmission** 

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

**Hand Brake** 

Left front

Left rear

Right rear

Suspension

Operation

Head lights Tail lights Indicators

Shock absorbers Air Conditioning / Heater

**Electrical / Accessories** 

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Suspension performance Steering performance

Spare

Right front

Coolant condition Performance

Radiator / Hoses (visual)

01 Jul 2019 Created:

Pass

1

~

/

V

1

Tyres (lowest observed tread depth of tyres)

N/A

1

mm

mm

mm

 $\mathsf{mm}$ 

7.0

7.0

5.0

5.0

1

/

/

/

~

1

1


Yes

Fail

Make: Toyota Model: Landcruiser Prado **Body Style:** SUV Year: 1998 Registration: HGU8 **Reg Expiry:** 23 Sep 2019 WoF Expiry: **Odometer:** 20 Aug 2019 422,238 Kms **Good No:** 17973716 VIN: JT711VJ9500045557 **Next Service:** Service History:

#### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



### **Body Inspection Comments**

R/H Headlight Cracked, Right side wheel Flares paint worn, W/Screen chips x 4 Right Side middle & left side, Centre console lid Broken,

Conditions During Body Inspection: Dry

## **Under Carriage & Under Bonnet Inspection Comments**

Oil seepage lower engine area, surface rust on under body of vehicle.

Interior Comments		
Seats	Poor	
Carpets	Average	
Panels	Average	
Dashboard	Average	

# **General Comments**

Inspected by:

**Road Conditions During Test Drive:** Dry

**Engine Timing Mechanism:** Cambelt

Chris Buckley

I have read and understood this condition guide.

**Evidence of Cam Belt Replacement:** 

	Remote locking	· /	
	Sat. Nav. (basic test only)	~	
Kms:	Reversing camera	V	
Date: 01 Jul 2019			
Name: Signature:			