

Report ID: 17,973,728 Version: 1 01 Jul 2019 Created:

Make:	Mazda	Model:	Mazda6	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2010	Registration:	FPY489	Reg Expiry:	21 Apr 2020	Engine				
WoF Expiry:	06 Dec 2019	Odometer:	196,009 Kms	Good No:	17973728	Oil level	V			
VIN:	JM0GH105200207214	Next Service:	202000	Service Histor	y: Yes	Smoke & fumes	V			
						Performance	r			
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	V			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~			
	SC		P SC S P	W	Р	Performance	~			
Key:	Bell	-0	F3C 3P			Radiator / Hoses (visual)	~			
S = scratch D = dent						Transmission				
D = dent R = rust	sc d			210	HIVS	Operation	~			
PT = paint defe						Noise	~			
C = crack					SC	Clutch			~	
P = pin dent	HIP				74114	CV joints	~			
* = decals	sc 916			The second		Wheel bearings	V			
SC = stone chips W = significant scuffs						Brakes				
w = significant	P SC W		P S		Р	Performance	~			
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
Body Inspection Comments						Tyres (lowest observed tread	d depth	of tyre	ès)	
						Left front	7.	.0	mm	
						Right front	7.	.0	mm	
						Left rear	6	.0	mm	
Conditions During Body Inspection: Dry						Right rear	4.0 mm		mm	
						Spare	No			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
/						Suspension performance	~			
						Steering performance	~			
Shock						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
Correcto	Good					Tail lights	~			
Carpets						Indicators	~			
Panels	Good					Dashboard warning lights	~			
	, Good					Wipers (front & rear)	~			
Dashboa	iu					Window winder FL	~			
						Window winder FR	~			
General C	<u>Comments</u>					Window winder RL	~			
/						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry Central locking							~			
			•			Remote locking	~			
Engine Timing Mechanism: Timing Chain Sat. Nav. (ba									~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
Inspected	Inspected by: Chris Buckley Date: 01 Jul 2019									

I have read and understood this condition guide.

Name:

Signature: