

Report ID: 17,974,906 Version: 2 18 Sep 2019 Created:

Make:	Mazda	Model:	Axela	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2007	Registration:	JWP708	Reg Expiry:	10 Dec 2019	Engine			I
WoF Expiry:	02 Aug 2020	Odometer:	173,122 Kms	Good No:	17974906	Oil level	~		
VIN:	7AT0C13JX16308130	Next Service:	183100	Service Histor	y: No	Smoke & fumes	~		
				· · · · · · · · · · · · · · · · · · ·		Performance	~		
	port is not a warranty	aration is made	for age and miloage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	✓		
						Performance	~		
Key:	S	-0	P R	-01-	s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	s sc			715	HIL PT	Operation	~		
PT = paint defe				$\left[\left(\right) \right]$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HIC				74114	CV joints	~		
* = decals	DSC 916			-No-		Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs SC W		SC S		Р	Performance	~		
Bodylas	ection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			es)
						Left front	6.0 mm		
						Right front	6.	0	mm
						Left rear	6.	0	mm
Conditions During Body Inspection: Dry						Right rear	6.	6.0 mr	
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Minor surfa	ce rust on under body o	of vehicle.				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments					Window winder RL	~			
/						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
			·			Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Chris Buckley Date: 12 Sep 2019									

I have read and understood this condition guide.

Name:

Signature: