

Report ID: 17,974,981 Version: 3 27 Sep 2019 Created:

| Make: | Mazda | Model: | Atenza | Body Style: | Sedan | | Pass | Fail | N/A |
|--|------------------------|-----------------|------------------------|---------------------------------------|----------------------|--|--------|------|-----|
| Year: | 2004 | Registration: | EJW998 | Reg Expiry: | 24 Jun 2020 | Engine | | | L |
| WoF Expiry: | 11 Oct 2020 | Odometer: | 158,018 Kms | Good No: | 17974981 | Oil level | ~ | | |
| VIN: | 7A8C1390708114804 | Next Service: | 162000 | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | avation is made | for one and miles as | Danta hava nat | heen discontined or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends | | | | | | Cooling System | | | |
| a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Coolant condition | | | |
| | | | | | | Performance | ~ | | |
| Key: | SC W | -0 | S D SC | \square | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent | S D SC | | | ZIS | S D | Operation | ~ | | |
| R = rust PT = paint defe | | | | $\left(\left \right\rangle \right)$ | | Noise | ~ | | |
| C = crack | | | | | SC | Clutch | | | ~ |
| P = pin dent | HIC | | | | 74 <u>11</u> | CV joints | ~ | | - |
| * = decals | sc 916 | | | -Jul- | | Wheel bearings | · · | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significan | t scuffs w | | P SC | JYW | SD | Performance | ~ | | |
| Bodylac | | Note: som | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | ~ | | |
| Body Inspection Comments | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| / | | | | | | Left front | 6.0 | 0 | mm |
| | | | | | | Right front | 5.0 | 0 | mm |
| | | | | | | Left rear | 5.0 | 0 | mm |
| Conditions During Body Inspection: Wet | | | | | | Right rear | 6.0 mm | | mm |
| Conditions Daming Dody inspection. Wet | | | | | | Spare | Yes | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| / | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | 1 1 | | |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| | Average | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Average | | | | | Dashboard warning lights | ~ | | |
| | , Good | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General C | <u>Comments</u> | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 1 | | |
| Road Conditions During Test Drive: Wet Central locking | | | | | | | ~ | | |
| | - | | | | | Remote locking | | | ~ |
| Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only) | | | | | | | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ |
| Inspected by: Chris Buckley Date: 17 Sep 2019 | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: