

Report ID: 17,975,038 Version: 1 19 Sep 2019 Created:

Make:	Ford	Model:	Territory	Body Style:	SUV		Pass	Fail	N/A	
Year:	2005	Registration:	CRS698	Reg Expiry:	30 Nov 2019	Engine				
WoF Expiry:	30 Nov 2019	Odometer:	139,425 Kms	Good No:	17975038	Oil level	~			
VIN:	6FPAAAJGAT4T95784			Service Histor		Smoke & fumes	~			
			149000		. 110	Performance	~			
	port is not a warranty						-			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Noise				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
						Coolant condition	~			
Key:	S SC		S S		S P	Performance	~			
S = scratch	~	(0)		300	$\checkmark$	Radiator / Hoses (visual)	~			
D=dent						Transmission			1	
R = rust	s sc				HIV	Operation	~			
PT = paint def	ect N				PT SC	Noise	~		<u> </u>	
C = crack						Clutch			~	
P = pin dent * = decals	PT SC DE				1845	CV joints	~			
SC = stone chi		10		70		Wheel bearings	~			
W = significant scuffs						Brakes				
	S	$\sim$	S S	W	S P	Performance	~			
Body Inst	pection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~			
R/F Fog Lamp Cracked , Hood lining sagging, L/F Guard lower moulding Broken ,					Tyres (lowest observed tread depth of tyres)					
					Left front	6	.0	mm		
						Right front	6	.0	mm	
						Left rear	3	.0	mm	
Conditions During Body Inspection: Dry						Right rear			mm	
Conditions During body inspection. Dry					Spare	Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Surface Rus	t on underbody of Vehi	cle, oil seepage l	ower engine area.			Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater	•			
						Operation			1	
Interior Comments						Operation   Electrical / Accessories				
	Good					Head lights			1	
Seats						3	~			
Carpets	Average					Tail lights	~			
	Average					Indicators	~			
Panels	/ verage					Dashboard warning lights	~			
Dashboa	Good Good					Wipers (front & rear)	~		<u> </u>	
						Window winder FL	~			
						Window winder FR	~			
General Comments Ignition Barrel Worn ,					Window winder RL	~				
ignition Bai	iei wom,					Window winder RR		~		
						Rear view mirrors		~		
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry						Central locking		~		
	2					Remote locking		V	1	
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~	
Inspecte	Inspected by: Chris Buckley Date: 18 Sep 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....