

Report ID: 17,981,287 Version: 1 16 Apr 2019 Created:

Make:	lsuzu	Model:	D-MAX	Body Style:	Utility		Pass	Fail	N/A
Year:	2013	Registration:	GTM549	Reg Expiry:	07 Apr 2019	Engine			
WoF Expiry:	05 Apr 2020	Odometer:	239,175 Kms	Good No:	17981287	Oil level	~		
VIN:	MPATFS85JDT002879	Next Service:	249200	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	.narge.	Coolant condition	~		
	SC		S P SC S SC		SC	Performance	~		
Key:	La C	-0	3730 330			Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	s sc			715	HIV	Operation	~		
PT = paint defe		F I		$\left(\left \left(\right) \right\rangle \right)$		Noise	~		
C = crack						Clutch	~		
P = pin dent	HIP				74116	CV joints	~		
* = decals	s sc 916			Tool .	ELC'S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = significant	S SC		S SC SC		SC	Performance	~		
Body Insr	paction Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
						Left front	5	5	mm
						Right front	7	7	mm
						Left rear	2	1	mm
Conditions During Body Inspection: Dry						Right rear	4 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Comoto	Average					Tail lights	~		
Carpets						Indicators	<		
Panels	Average					Dashboard warning lights	~		
	rd Average					Wipers (front & rear)	~		
Dashboa	ru					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	3		
Road Conditions During Test Drive: Dry						Central locking	~		
		<u> </u>	•			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
Inspected by: Donovan Matara Date: 16 Apr 2019									
Inspected by: Donovan Matara Date: 16 Apr 2019									

I have read and understood this condition guide.

Name:

Signature: