

Report ID: 17,981,819 Version: 1 05 Apr 2019 Created:

Make:	Mazda	Model:	Mazda6	Body Style:	Wagon		Pass	Fail	N/A
Year:	2008	Registration:	KLC869	Reg Expiry:	15 Feb 2019	Engine	I	L	I
WoF Expiry:		Odometer:	220,479 Kms	Good No:	17981819	Oil level		~	
VIN:	JM0GH10F100104285	Next Service:	-	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		¢ 1 1			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			[
						Performance	~		
Key:	W	-0	S P SC S P W		w	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent S PT C P SC D S C SC W						Operation	~		
R = rust				10	JHIH	Noise	~		
PT = paint defe C = crack	ect III			+	SC	Clutch	V		
P = pin dent	Ho	KI			JIII —	CV joints	~		~
* = decals	sc pp			AL-	ELIP SC	Wheel bearings	-		
SC = stone chips							~		
W = significant scuffs W S S PW P SC S PT SC						Brakes			1
		Nata				Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	s may not be disp	hayed in the diagram	Hand Brake		<i>с.</i>	Ļ
Headlights need attention, scuff marks on left wing mirror, right tail lights broken, stone chips in the windscreen, back tires are balding,						Tyres (lowest observed tread depth of tyres)			
windscreen	, back tires are baiding,					Left front		5	mm
						Right front		5	mm
						Left rear	-		mm
Conditions During Body Inspection: Dry						Right rear	2 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare			
<u>Under Ca</u>	image & Under Bor	inet inspectic	on comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation		~	
Interior Comments stains in the rear					Electrical / Accessories				
Seats	stains in tr	ie rear				Head lights	~		
Carpets	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	wear and t	tear				Dashboard warning lights	~		
Dashhar	Average					Wipers (front & rear)	~		
Dashboa	iiu y					Window winder FL	~		
	_					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR		>	
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
			•			Remote locking		~	
						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected	Inspected by: Donovan Matara Date: 05 Apr 2019								

I have read and understood this condition guide.

Name:

Signature: