

Report ID: 17,981,826 Version: 1 16 Apr 2019 Created:

Make:	Holden	Model:	Crewman	Body Style:	Utility		Pass	Fail	N/A
Year:	2007	Registration:	FAD835	Reg Expiry:	28 Jul 2019	Engine			
WoF Expiry:	11 Apr 2020	Odometer:	158,492 Kms	Good No:	17981826	Oil level	~		
VIN:	6G1ZK34B96L975016	Next Service:	168400	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	s sc s sc	-01-	S SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	- HE			ZIS		Operation	~		
R = rust PT = paint defe				$\left(\left \right\rangle \right)$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HID				게	CV joints	~		
* = decals	SPSC 916			- Jul		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC S SC S SC						Performance	~		
Dedulmen		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			L
									mm
						Right front	6		mm
						Left rear	5		mm
Conditions During Body Inspection: Dry						Right rear	6 mm		-
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Seats drivers seat ripped, wear and tear, minor stains ,					Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators	~		
Demolo	Average					Dashboard warning lights	~		
Panels						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		<u> </u>
	I					Window winder FR	~		$\left - \right $
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RE	~		<u> </u>
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys			
						Central locking	2		
Road Conditions During Test Drive: Dry						Remote locking	v		<u> </u>
Engine Tir	ming Mechanism:	Timing	Chain				~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
						Reversing camera			~
Inspected by: Donovan Matara Date: 16 Apr 2019									

I have read and understood this condition guide.

Name:

Signature: